

ASS. REQ. BY:

Tang Jiah

REF:

CT1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Chwang

Veh No: SH60911E Yr Regn: 2017 Dec.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40. c.c. 1685

Colour: Blue. A/C: Insured / Std / NI / NA

Sp. Reading: 469316 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLB41UMH4A7765

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 175

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook.

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 8/6/20@355pm

Survey held at Comfortelgoyung

Des. of Damages: Frt / Rear NO/S / NI / U/C / Roof top or

O/S Rear.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Report Form:

Lump Sum / B.B. /

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

40, Bras Basah Road, Singapore 179571

Telephone : 65 4340 8280 Fax : 65 4340 8700

Workshops

24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100

24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100

A member of COMFORTDELGRO

Date/Time: 06.06.2020 11:37

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO 305403035

STOMER
/MS COMFORT TRANSPORTATION PTE LTD
STOMER NO 7010045
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755


REGN NO	SH 6091E	MILEAGE
MAKE	HYUNDAI	FUEL
MODEL	I-40	DATE TIME IN
YR OF MANU	13.12.2017	TARGET DATE
CHASSIS CODE	KMHLB41UMHU097765	COMPLETION DATE/TIME

COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 05.06.2020
NATURE: 3P 05.06.2020

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No: SH 6091E CHIANG

Vehicle No: SH 6091E

Signature/Date

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard