

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
WEI LEE MOTOR WORKS			Ref : CS/TP20006242/K	sf3e2	
BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644			Date: 19-06-2020		
	EHALF OF KH LE	ASING PTE. LTD.	Code: TP389		
1.	·				
	Insured Veh.		Veh. Inspected	SJY 863B	
	Policy No.		Coverage (\$)	0.00	
	Claim No.		Excess (\$)	0.00	
	Assign From		Assign Date	30/04/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA WISH (A)	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	ZGE200015673	Colour	METALLIC GREY	
	Odometer	208058	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	NEXEN	8 mm	
	L/H Front Tyre	195/65 R15	NEXEN	8 mm	
	R/H Rear Tyre	195/65 R15	NEXEN	8 mm	
	L/H Rear Tyre	195/65 R15	NEXEN	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S AND FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	21/04/2020	Inspection Date	30/04/2020	
	Survey held at	WEI LEE MOTOR WORKS			
		BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				