



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN			Ref: CC4/ASM20006253/Kes3q2 Date: 20/12/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 4567A	Veh. Inspected	SLS 4454E	
Policy No.	P2067982	Coverage (\$)	0.00	
Claim No.	S0M02P2Z	Excess (\$)	0.00	
Assign From		Assign Date	11/06/2020	
2. Vehicle Particulars & Condition				
Make & Model	KIA CARENS (A)	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KNAHU815VJ7190236	Colour	METALLIC SILVER	
Odometer	198041 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	CST	8 mm	
L/H Front Tyre	205/55 R16	CST	8 mm	
R/H Rear Tyre	205/55 R16	CST	8 mm	
L/H Rear Tyre	205/55 R16	CST	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/06/2020	Inspection Date	11/06/2020	
Survey held at	LIAN HONG SENG MOTOR WORKS BLK 5035 ANG MO KIO IND.PARK 2 #01-345 SINGAPORE 569537			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	