

PRS

ASS. REC. BY: Mr. Lim | REP: ES3/LPC20004670/Bvd3-1 | Special Instruction: 15/6/20

ASSIGNMENT (Office)

From (Person): Gerald Poh of LPC Date/Time: 30/3/2020 11:35am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SBY 9368A Insured: SFB 3344G

at Workshop n/s Hiap Lek Automobile Tel: 4660 1347

of 160 Sin Ming Drive # 05-17

Policy No: _____ Claim No: 19/20/20/VP05/023257

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27/03/2020

(Client's Record) 1wp

CA / REV / REP. / REV 24 HRS

Date/Time: 11:56am 30/3/2020 Person Contacted: Mr. Ong Vehicle: IN/OUT

Date/Time	Action/Instruction	Signature
	SBY 9368A - NR/11/20/20/20/20/20	12/03/27/03/2020
	SFB 3344G - NR/11/20/20/20/20/20	12/03/27/03/2020
<u>2/4/20</u>	Submit PRS	

18/6/20 Submit LS \$2250, 4 days (Red 2200, 49%)

RECEIVED 02 APR 2020

ASS. REC. BY:

REF:

LPC

Vern

ASSIGNMENT

From:

Date: 30/3/2020

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SBY 9368A

at Workshop m/s Hiap Lek Automobiles

of 160 Sin Ming Drive #05-17

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

53000/2

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SBY 9368A

Yr Regn:

2/11/2015

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Qashqai

C.C. 1197

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading:

50207

T/Radio: Insured / Std / NI / NA

Eng/No:

HRA2186497A

C/No:

SJNFEAN1141478432

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/60/17

R: 215/60/17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

27/3/2020

D.O.I.

30/3/2020

Survey held at

Hiap Lek Auto

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV 53000/2

PV 41,372/2

NV 11,628/2

TC 11/11

30/3/2020

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 18/6/20-Typist

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Rep. Format: TP

Lump Sum / I.B.C.: LS \$2250