

12/12/2019

ASS. REC. BY

Singapore: AMO QIC/PR

REF: 033/FWD20004266

al Instruction:

PRS

From (Person):

Lionel Tan

ASSIGNMENT (Office)

of FWD

Date/Time

09/06/2020 13:41 PM.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SLJ 4680R

Insured:

SLL 9670B

at Workshop m/s

KOI Motor

Tel:

92781189

of 176 Sin Ming Drive # 04-12

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17/03/2020

CA / REV / REP. / REV 24 HRS lap

H.O.D. Endorsement:

Date/Time: 1:05pm @ 14/3/2020

Person Contacted:

ERIC

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (X)
	SLJ 4680R - X	
	SLJ 9670B - X	
	Submit PRS Report	

Dismantle part: 20/03/2020

After repair: 25/03/2020

RECEIVED 20 MAR 2020

600.
PHS

REF: FWD CS3/FWD 2000 4266/G4d3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s KOI Motor
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ4680R yr Regn: 12, 2006
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Toyota Ahi's 1.6 c.c 1598
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 171820 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MR053 ZEC 107137225
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 185/70R14
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front: _____ Rear: _____
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. _____ D.O.I. 18-07-20
Survey held at w/s 3pm
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/3 GIA later Give.
\$4000 - \$5000
24/3/2020

\$2700 - 5 days (RED:6600;70%)

Date/Time, File Pass to?



: Preli. Report

11 26/3 Typist



: Final Report

Date/Time, File Return to?

2

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Wheel and

Survey Fee:

Transportation:

S + RS SI

Fuel

Other:

TOTAL:

80
90
90
180

Report Format:

PHS

Emp. Sum / M.B.: