

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305404522

Date : 16/06/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : TAUFIKH

Vehicle Reg No. : SHC1972C

Date of Accident : 12-Jun-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SMC7429G

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,727.22

(b) Labour Charges \$1,070.00

Total for Part-By-Part Repair Cost \$2,797.22

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : TAUFIKH

Date : 22/6/20

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305404522
 REGN NO : SHC1972C
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 19.12.2019
 DATE/TIME IN : 12.06.2020 12:50
 ACCIDENT DATE : 12.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52
0002	04-01-0104-2533-G	REAR BUMPER CENTER-Black	1	451.25	20.00	361.00
0003	04-01-0104-2288-G	REAR BUMPER REINFORCEMENT	1	294.80	20.00	235.84
0004	04-01-0104-2545-G	REAR BUMPER LWR MOULDING	1	155.00	20.00	124.00
0005	04-01-0104-3819-G	REAR BUMPER STAY LH	1	138.10	20.00	110.48
0006	04-01-0104-3919-G	REAR BUMPER STAY RH	1	138.10	20.00	110.48
0007	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60
0008	04-01-0104-2270-G	TAILGATE EMBLEM-HYBRID	1	24.30	20.00	19.44
0009	04-01-0104-2271-G	TAILGATE EMBLEM-IONIQ	1	31.30	20.00	25.04
0010	28-01-0103-0005-A	TAILGATE COMFORTDELGRO	1	30.00	10.00	27.00
0011	28-01-0103-0006-A	TAILGATE 65521111	1	30.00	10.00	27.00
0012	28-01-9999-2025-A	TAILGATE APPS	1	40.00	10.00	36.00
0013	04-01-0104-2544-G	REAR BUMPER TOW COVER	1	5.40	20.00	4.32

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305404522
REGN NO : SHC1972C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 19.12.2019
DATE/TIME IN : 12.06.2020 12:5
ACCIDENT DATE : 12.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0104-1150-A	REAR BUMPER MAT	1	50.00		50.00
0015 09-01-9999-0068-A	REVERSE SENSOR	1	180.00	10.00	162.00
0016 FNPS	NO PLATE(S)W/TRIM COVER*	1 N	55.00	10.00	49.50

SUB-TOTAL : 1,727.22

JOB NATURE

0000 PB	PANEL BEATING-TAILGATE ETC		640.00
0001 SP	SPRAYPAINT CHARGE		400.00
0002 L	R/I REVERSE SENSOR		30.00

SUB-TOTAL : 1,070.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305404522
REGN NO : SHC1972C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 19.12.2019
DATE/TIME IN : 12.06.2020 12:5
ACCIDENT DATE : 12.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,797.22



MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE
DATE :