

Our Job Ref No 305404976Date : 16.06.20ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : Mr TAUFIKHVehicle Reg No. SH9432K CTPL12.06.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG --- FBM9587Y

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%\$1,150.00**Final Lumpsum Repair cost**\$1,150.003. Estimated normal period for repairs: 2 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and  
finalized amountSignature : Name : LIM KWOK ENGTel : 62148316Fax : 65468156

Signature : \_\_\_\_\_

Name : \_\_\_\_\_

Date : \_\_\_\_\_

**For Official Use Only**

| Item                                                    | Amount | Document Attached<br>Yes or No | Confirm By<br>(Signature) | Remarks |
|---------------------------------------------------------|--------|--------------------------------|---------------------------|---------|
| 1. Rental Rate P/Day                                    |        | YES                            |                           |         |
| 2. Loss of Income Paid                                  |        | NO                             |                           |         |
| 3. Survey Fees                                          |        |                                |                           |         |
| 4. LTA Search Fee                                       | \$7.49 |                                |                           |         |
| 5. Medical Fees (on behalf<br>of driver, if applicable) |        |                                |                           |         |
| 6. Overrun                                              |        |                                |                           |         |

Remarks:

\_\_\_\_\_  
\_\_\_\_\_

Lke

AIG

COMFORTDELGRO ENGINEERING PTE LTD

Date: 15.06.2020

REPAIR ESTIMATE

Time: 14:52:21

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305404976  
 REGN NO : SH 9432K  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 12.05.2016  
 DATE/TIME IN : 15.06.2020 09:25  
 ACCIDENT DATE : 12.06.2020

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0103-2322-A I40V3 BUMPER W LIP &amp; FOG 1 1,052.20 20.00 841.76 de✓

0002 04-01-0101-0111-G HYUNDAI BUMPER COVER CLIP 10 L 22.00 20.00 17.60 re✓

0003 04-01-0103-0638-G I40VC BRKT ASSY-FR BPR UP 1 22.40 20.00 17.92 X

0004 04-01-0103-0654-G I40V2 COVER-FR FOG BLANKI Rhl 1 93.60 20.00 74.88 cut✓

SUB-TOTAL : 952.16

1,167.80  
 -20%  
 934.24

## JOB NATURE

0000 L PANEL BEATING 350.00

0001 23-502 SPRAYPAINT ON AFFECTED AREA

250.00 200

SUB-TOTAL : 600.00

480  
 1,414.24  
 -20%  
 1,131.39

TOTAL : 1,552.16

MVA NAME &amp; SIGNATURE

DATE :

SURVEYOR NAME &amp; SIGNATURE

DATE :

AUTHORISED : YES / NO

Tan Sri 97495789  
 - WP' 15/6/2020 4pm  
 Lump sum \$1,150  
 Resinny after repair  
 02 days.