

COMFORTDELGRO ENGINEERING

Our Ref : 305403039

Date : 08/06/20

Time of Fax : _____

Via Fax : Email

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Workshop

→ AIG

Attn : Motor Claims Dept.

Dear Sirs

Your Insured : SLQ6400H

Date of Acc : 03/06/20

* 7 pages

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SHA1837X

Loyang
59 Loyang Drive
Singapore 508969

1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.

2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

3 Enclosed, please find :

- I) Our initial estimate of repairs of the damaged vehicle.
- II) Accident report made by our client.

4 I would appreciate it if you could call us to arrange for the survey of the vehicle

→ Lim Kwok Eng, Tel no. 62148355 or Hp no. 98240811
Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305
Lim Tien Siong Tel no. 62148398 or Hp no. 96358546
Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006
Fauzy Bin Mokhtar Tel no: 62148319 or Hp no : 81259176
Larry Ng Tel: 6214 8316

5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.

6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

7 Thank you.

Yours faithfully



for Vice President

Crash Repairs & Claims Recovery

A member of

COMFORTDELGRO

