

Lke

AIG

LKK

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305403039
 REGN NO : SHA1837X
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 28.04.2016
 DATE/TIME IN : 08.06.2020 10:40
 ACCIDENT DATE : 03.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1 L	1,052.20	20.00	841.76	de ✓
0002 04-01-0103-0637-G	I40VC BRKT ASSY-FR BPR UP	1 L	22.40	20.00	17.92	?
0003 04-01-0103-0639-G	I40VC BRACKET-FR BUMPER S	1 L	24.60	20.00	19.68	?
0004 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	246.00	20.00	196.80	na ✓
0005 04-01-0103-0781-A	I40VC LAMP ASSY-HEAD LH#	1 L	1,388.00	20.00	1,110.40	X Not consistent
0006 04-01-0103-2164-A	I40V3 GRILLE ASSY-RADIATO	1 L	1,480.00	20.00	1,184.00	na ✓
0007 04-01-0103-2175-G	I40V3 SYMBOL MARK-H	1 L	39.50	20.00	31.60	na ✓
0008 FNPS	NO PLATE(S)	1 N	25.00	2.00-	25.00	na ✓
0009 FNPS	NO PLATE(S) TRIM COVER (F	1 N	30.00	0.20	30.00	na ✓

SUB-TOTAL : 3,457.16

JOB NATURE

0000 L	PANEL BEATING	350.00	280.
0001 23-502	SPRAYPAINT ON AFFECTED AREA	250.00	200.

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305403039
REGN NO : SHA1837X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 28.04.2016
DATE/TIME IN : 08.06.2020 10:4
ACCIDENT DATE : 03.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0002 17-01 CHECK ALL LIGHTING

50.00 30

SUB-TOTAL : 650.00

TOTAL : 4,107.16

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanfer 97495744
02 days
Lumpsum
Resurvey after repair
tanfer @ lkkauto.com.
8/6/20 @ 330

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO 305403039

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755


REGN NO	SHA1837X	MILEAGE
MAKE	HYUNDAI	FUEL
MODEL	I-40	DATE TIME IN
YR OF MANU	28.04.2016	TARGET DATE
CHASSIS CODE	KMHLB41UMGU087854	COMPLETION DATE/ TIME

AIG

Accident Date: 03.06.2020
NATURE: 3P 03.062020

JOB DESCRIPTION

/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Delivery Slip

Exit Pass

SHA1837X

LKE

Vehicle No.:

SHA1837X

Service Advisor

Signature/Date

Name of Service Advisor

Date

To be kept by Security Guard