

220012002

CS3/LPC20001081/Qvf3-1

REF:

CS3/LPC20001081/Hvd3<sup>52</sup>

Special Instruction:

ASS. REC. BY:

Surveyor:

~~Hock An~~

Sun Pin

ASSIGNMENT (Office)

16/6/20

From (Person):

Gerald Poh

Kenny Lim

LPC

Date/Time:

17/01/2020 @ 8:29am

Estimated Cost:

Bill to:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 22892

Insured:

XE 777G

at Workshop m/s

My Car Consultant

Tel:

8866 8832

of

53 ubi Ave 1 # 01-33

Policy No:

Claim No:

19/20/20 / VC00/022910

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14.1.2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:51am @ 17/1/2020

Person Contacted:

Hui Qin

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimated X

SLA 22892 - NA/FWD 20000972/24

D.O.A. 14/01/20

XE 777G - NA/FWD 20000972/24

D.O.A. 14/01/20

17/1/20 → survey taken

17/1/20 → Repair taken

1/1 →

19/6/20 Submit LS \$11,300, 8 days (Red 8600, 43%)

ASS. REG. BY:

A-ANN

(REP):

IPC

PRS

# ASSIGNMENT

From:

Date:

17/01/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLA 2289Z

at Workshop m/s

My Car Consultant

of

53 ubi Ave 1 # 01-33

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLA 2289Z

Yr Regn:

5/21/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

VOLKSWAGEN JETTA

C.C.

1370

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

85707km

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZ16Z 9M009783

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55/R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6 Yoko mm

L/Bal.

6 mm

D.O.A.

14/1/20

Rear

R/Bal.

6 Yoko mm

L/Bal.

6 mm

D.O.I.

7/1/20

11.43km

Survey held at

my car consultant

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/1/2020

repair days → 7 days  
Submit PRS report

\* SLA 2289Z  
PRS case

RECEIVED 21 JAN 2020

MV - 62000

PV - 50611

NV - 11300

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 20/1 - typist

19/6/20-Typist

Report Format:

TP

Lump Sum / L.E.R.:

LS \$11,300

Days Of Repair: 8

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invt (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$1

Photos

Other:

TOTAL