

ASS. REC. BY:

REF:

ASSIGNMENT

390K
GBC XPIR: 2021/04/04

From: _____ Date: _____

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 2311A

at Workshop m/s: Comfort Delibros

of 45, Pandan Loop

Insured: Aurore

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: TPA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 6K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBC 2311A Yr Regn: 2011 / 04/04

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: FIAT DOBLO CARNO 1.3M c.c. 1248

Colour: MULTI A/C: Insured / Std / NI / NA

Sp. Reading: 260580 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2FA 263000009110280

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ROADSTONE

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 10/06/2020 D.O.I. 16/06/2020

Survey held at COMFORT PANDAN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LUMP SUM \$2000, 4DAYS (red: 121.33; 71%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Rep. Formel:

Lump Sum / L/S: L/S 2000

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

COMFORT DELGRO
ENGINEERING

45 Pandan Road S (609286)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : ☒ Own Damage
☐ 3rd Party
☐ Windscreen

Ins Company : AWAC
Excess : T.B.A
Date of Accident : 26.05.2020
Suggested Days of Repair : 10 Day

Vehicle No. : GBC2311A
Make & Model : FIAT / DOBLO CARGO 1.3MJ
Year of Manufacture : 2011
Chassis No. : ZFA26300009110280
Engine No. : 199A30004174966
Policy No. : BVFCSB0013691900
Time of Accident : 18.50 P.M

In-house Vehicle Assessor

Name : Wong Chee Wei

Signature :

Contact No : 68676924
HP : 97239882

Repair Estimates

Parts (a) Cost / List Price Items \$3,228.49
Plus/Less 10 % \$322.84
(b) Nett Price Items
Less %
(c) Special Nett Items \$1,300.00
Total Parts Cost (Appendix A) \$4,851.33
Labour (Appendix B) \$2,270.00
Total Repair Cost \$7,121.33

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Name of Surveyor :

Company :

Survey conducted on :

RASUL

LKK

16/06/2020

Acknowledged by Repairer

Signature:

Date:

1800

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4 day(s)

(c) Resurvey : ☒ Required ☐ Not Required

(d) Excess :

T.B.A

(e) Signature of surveyor :

R

Date: 16/06/2020

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandan Road S (609286)

Tel: 68676919 Fax: 62626950

Appendix A

Spare Parts

Vehicle No. : GBC2311A Submit By : Wong Chee Wei
 Make & Model : FIAT DOBLO CARGO 1.3MJ Year Manufacture : 2011
 Chassis No. : ZFA26300009110280 Engine No. : 199A30004174966

OD

S/Order

S/No	Part Description	Qty	Cost Price		Nett Price	List Price	S- Nett Price
			original	make up 10%			
1	RHS TAIL GATE <i>bt</i> ✓	1	\$1,074.94	\$1,182.43			
2	RHS TAIL GATE TOP LOCK <i>X</i>	1	\$108.93	\$119.82			
4	RHS TAIL GATE LOWER LOCK <i>X</i>	1	\$81.88	\$90.06			
5	RHS TAIL GATE SIDE WEATHERSTRIP <i>new</i> ✓	1	\$133.32	\$146.65			
7	RHS TAIL GATE UPPER HINGE <i>X</i>	1	\$108.93	\$119.82			
8	RHS TAIL GATE LOWER HINGE <i>X</i>	1	\$118.93	\$130.82			
9	LHS TAIL GATE <i>repair bt</i> ✓	1	\$1,083.34	\$1,191.67			
10	LHS TAIL GATE CENTER LOCK <i>X</i>	1	\$137.52	\$151.27			
11	BODY SIDE WEATHERSTRIP <i>X</i>	1	\$203.78	\$224.15			
12	STICKER - COMPANY DECAL - BACK, RHS&LHS FENDER (<i>not covered</i>)						<i>X</i> \$1,200.00 <i>600</i>
13	RHS TAIL GATE GLASS <i>50</i> ✓	1	\$176.92	\$194.61			
14	SEALANT	1					\$40.00
15	BODY SEALANT	1					\$60.00 <i>40</i>
16		1					
17		1					
18		1					
19		1					
20		1					
21		1					
22		1					
23		1					
24		1					
25		1					
26		1					
27		1					
28		1					
29		1					
30		1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Appendix B

Tel: 68676919 Fax: 62626950,68676903

Vehicle No. : GBC2311A Submit By : : Wong Chee Wei
Make & Model : FIAT Year of Manufacture : 2011

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/06/2020 16:54
Date Of Accident	10/06/2020 13:30
Exact Location Of Accident	HDB TAMPINES BLK 496A (MSCP)TM3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC2311A
Insured/Policyholder	
Name Of Registered Owner	F&N FOODS PTE LTD
Co Reg No	1XXXXX390K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64612425

Vehicle Particulars

Manufacturer	FIAT
Model	DOBLO-1.6 D CARGO MJ (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	BVFC5B0013691900
Cover Note Number	

Driver

Name of Driver	CHAN YEE CHUEN
Passport No/FIN	GXXXX093N
Date Of Birth	21/09/1993
Occupation	OUTDOOR
Date Of Driving Pass	01/10/2018
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82186051
Fax Number	
Contact Number	
Email Address	NOEMAIL

214 PANDAN LOOP SINGAPORE

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 1
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

Sketch Plan Pg. 1
SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


F & N FOODS PTE LTD
214 Pandan Loop
Singapore 128405
Tel No. 6210 8108

COMINTOELCO ENGINEERING PTE LTD
EXTERNAL BUSINESS DIV. PANDAN BRANCH
NAME & SIGNATURE: 
DESIGNATION: _____ DATE: 18/6/2

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While coming to the parking lot and Reverse parking
 accidentally hit on the Rear corner wall.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 214 Pandan L.
 Singapore 280
 Tel No. 6210 6

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

CONVEX/DELORO ENGINEERING PTE LTD
 EXTERNAL BUSINESS UNIT
 NAME & SIGNATURE: [Signature]
 DESIGNATION: [Signature] 10/6/20

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



Used 2013 Fiat Doblo 1.3M for Sale



Merimen e-Claims



PARF/C

armart.com/used_cars/info.php?ID=874485&DL=3432

Fiat Doblo 1.3M

Overview

Financial

Accessories

Similar

Research

Photos

Map

WHOLESALE
EXPERIENCE AT YOUR
CONVENIENCE

Price	\$19,800	Lifespan	22-Oct-2033
Depreciation	\$5,910 /yr View models with similar depre	Reg Date	23-Oct-2013 (3yrs 4mths 6day COE left)
Mileage	N.A.	Manufactured	2013
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$12,466 as of today (change)	OMV	\$17,945
COE	\$37,205	ARF	\$898
Engine Cap	1,248 cc	No. of Owners	2
Curb Weight	1,360 kg		
Type of Vehicle	Van		

Features

View specs of the Fiat Professional Doblo Cargo (2014)

Doblo

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	390K

Vehicle No.:	GBC2311A
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jun 2020
Vehicle Make:	FIAT
Vehicle Model:	DOBLO CARGO 1.3MJ
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	199A30004174966
Chassis No.:	ZFA26300009110280
Maximum Power Output:	-
Open Market Value:	\$18,258.00
Original Registration Date:	02 Aug 2011
First Registration Date:	02 Aug 2011
Transfer Count:	0
Actual ARF Paid:	\$913.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	01 Aug 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$34,502.00
COE Rebate Amount:	\$3,886.00
Total Rebate Amount:	\$3,886.00

The information contained herein is correct as at 16 Jun 2020

OK