

ASS. REC. BY:

REF: CT2/2000 8328/Kg

Henneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Cheng Hoe

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

1317 / 1pm @ 310d Carpm (Red \$1374, 31%)
 20/07/20@12.37pm revised to Andeline Chng via Merimen.

Date/Time, File Pass to? ☐ : Prel. Report1) 20/07 Typist ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: MER-TP

Lump Sum H.B.T. (\$) 3100Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S - RS. \$ _____

Fees: _____

Others: _____

TOTAL

Veh No: SIN 2882S Yr Regn: 05, 17Type: ☒ M/Car ☐ M/Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Trailer or _____

Make: Honda Vezel c.c. 1496Colour: M. Blue A/C: ☐ Insured ☐ Std ☐ NI ☐ NASp. Reading: 114600 T/Radio: ☐ Insured ☐ Std ☐ NI ☐ NA

Eng No: _____

C/No: KU 1 1205190Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ BurntSteering: ☒ Inoper ☐ Jammed ☐ Leaked ☐ Burnt orBrake: ☒ Inoper ☐ Jammed ☐ Leaked ☐ Burnt orModi: ☐ Nil ☐ S/Rlm ☒ STD ☐ A/Rlm or

Tyre Size: F: _____

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Firestone


Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 15/6/20Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 m

The U/C / Chassis frame / Body Structure affected due to collision.

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
CITICON CONSTRUCTION PTE LTD

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM		Ref. No:	TP/CHINA (GBB5256L)
Claim Type:	THIRD PARTY	Date of Loss:	15/06/2020
Policy No:		Driveable?	
Vehicle Reg. No.:	SLN2882S		
Party At Fault:	UNKNCWN		
Driver (TP):	HOO SENG HIN DANIEL		
Make/Model:	HONDA VEZEL, 1.5 (A)	Vehicle Reg. Date:	04/05/2017
Vehicle Colour:	BLUE	Chassis No:	RU11205190
Engine No:	L15B4405191		
Odometer:	0 KM		
Paint Type:	NO		
Total Loss?	0		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	I WAS DRIVING ALONG CLIVE STREET WHEN M/LORRY GBB5256L SUDDEN DASH OUT FROM DUNLOP STREET AND HIT ONTO THE FRONT RH PORTION OF MY CAR. NO ONE WAS INJURED.		
Remarks:	VEHICLE SENT INTO ANG MO KIO WORKSHOP ON 15/06/2020		
Present Location:	CHENG HOE MOTOR PTE LTD (AMK)		

COST OF CLAIMS	Amount
Parts	2,704.00
Miscellaneous Items	150.00
Labour	1,620.00
Paintwork Labour	0.00
Towing	0.00
LKK Auto Consultants hence notify the Repairer of the following:	
• To resurvey before/after spray painting	
• To display damaged part(s) during resurvey	
• Parts prices are subject to confirmation	
• Third party survey is on a "Without Prejudice" basis	
• No illegal modification(s) is allowed	
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
Acknowledged by Repairer	
Signature:	
Date:	
Gross Total (\$\$)	4,474.00
+ GST 7.00% (\$\$)	313.18
Nett Amount (\$\$)	4,787.18

This claim is handled by: DORLYN LI YAZHU

Generated using Merlmen e-Claims Internet Estimation & Adjusting System

Version: 1.0 (Last Synchronised: 16 Jun 2020)
 M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
 Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SLN2882S/16/06/2020 11:03

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc front RH fender	0.00	0.00	*190.00 F
2	1		*1 pc front RH fender inner shield	0.00	0.00	*80.00 F
3	1		*6 pcs front RH fender inner shield clips @ \$2/pc	0.00	0.00	*12.00 F
4	1		*1 pc front RH fender wheel arch garnish	0.00	0.00	*55.00 F
5	1		*1 pc RH headlamp	0.00	0.00	*830.00 F
6	1		*1 pc front RH door	0.00	0.00	*530.00 F
7	1		*1 pc front RH door frame sticker	0.00	0.00	*12.00 F
8	1		*1 pc front RH door checker	0.00	0.00	*40.00 F
9	1		*1 pc front RH door top hinge	0.00	0.00	*30.00 F
10	1		*1 pc front RH door side mirror outer cover	0.00	0.00	*60.00 F
11	1		*1 pc front RH rim	0.00	0.00	*350.00 F
12	1		*1 pc front RH shock absorber	0.00	0.00	*220.00 F
13	1		*1 pc front RH knuckle arm	0.00	0.00	*195.00 F
14	1		*1 pc front RH wheel bearing	0.00	0.00	*100.00 F
Total Parts (\$\$)						2,704.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SLN2882S/16/06/2020 11:03. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 set sun shade	120.00
Sub Total (\$\$)			150.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	Remove & refix front bumper & attachments,headlamps,frt RH fender,frt RH door & attachments;knocking & repair front RH fender inner panel & realign bonnet the same	New	600.00
2	Putty & respray front bumper,front RH fender & inner panel,frt RH door,RH side mirror & all affected areas	New	700.00
3	Remove & refix front RH door window glass & reset central locking	New	60.00
4	Remove & refix front RH wheel,undercarriage & realign the same	New	150.00
5	To conduct computer wheel alignment	New	60.00
6	Rustproofing	New	60.00
Gross Labour Cost (\$\$)			1,620.00

Cheng Hoe Motor Pte Ltd/SLN2882S/16/06/2020 11:03. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/06/2020 16:23
Date Of Accident	15/06/2020 14:30
Exact Location Of Accident	JUNCTION OF CLIVE ST & DUNLOP ST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN2882S
Insured/Policyholder	
Name Of Registered Owner	HOO SENG HIN DANIEL
NRIC No	SXXXX040J
Email Address	DANHOOSH@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98581368
Alternative Phone No	OTHERS-63888310

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108126731-01 DC
Cover Note Number	04/05/2020 - 03/05/2021

Driver

Name of Driver	HOO SENG HIN DANIEL
NRIC No	SXXXX040J
Date Of Birth	27/05/1962
Occupation	OUTDOOR
Date Of Driving Pass	28/06/1980
Driving Experience	39 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98581368
Fax Number	
Contact Number	OTHERS-63888310
EMail Address	DANHOOSH@YAHOO.COM.SG

BLK 250B COMPASSVALE ST #07-73
Address 542250
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own
Vehicle
Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle)
involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by
ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s)
soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

I WAS DRIVING ALONG CLIVE STREET WHEN M/LORRY GBB5256L SUDDEN DASH OUT FROM DUNLOP STREET AND
HIT ONTO THE FRONT RH PORTION OF MY CAR. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: RETRIEVING
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBB5256L
Vehicle Make/Model/Colour NISSAN CABSTAR
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver TAN PUAY YOK
NRIC/Passport Number SXXXX188H
Contact Number
Address BLK 212 HOUGANG ST 21 #04-345
Postcode 530212
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)