

CYNA-LKK C/P

COMFORTDEL GRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 12.06.2020
Time: 10:29:03
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305404148
REGN NO : SHC7883L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 27.11.2019
DATE/TIME IN : 11.06.2020 15:40
ACCIDENT DATE : 11.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2534-G	COVER-FR BUMPER#	1	430.90	20.00	344.72	de ✓
0002 04-01-0104-2971-G	BRACKET-FR BUMPER SIDE SU	1	35.00	20.00	28.00	de ✓
0003 04-01-0104-2361-G	MOULDING-FRONT BUMPER CTR	1	188.00	20.00	150.40	car ✓
0004 04-01-0104-2915-G	LAMP ASSY-HEAD RH#	1	1,993.65	20.00	1,594.92	cut ✓
0005 04-01-0104-4991-G	LAMP ASSY-DAY RUNNING LIG	1	642.50	20.00	514.00	?
0006 04-01-0104-0633-G	MOULDING-FRONT BUMPER RH	1	93.00	20.00	74.40	cut ✓

SUB-TOTAL : 2,706.44

JOB NATURE

0000 PB	PANEL BEATING	500.00	320
0001 SP	SPRAYPAINT CHARGE	300.00	200
0002 17-01	CHECK ALL LIGHTING	50.00	30

SUB-TOTAL : 850.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 12.06.2020

Time: 10:29:03

Page: 2

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305404148
REGN NO : SHC7883L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 27.11.2019
DATE/TIME IN : 11.06.2020 15:4
ACCIDENT DATE : 11.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,556.44

MVA NAME & SIGNATURE
DATE: 12/6/20

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE:

Tanpin 97495749
wp'

12/6/20 @ 1150

02 days

P/P Resurvey before paint

tanpin @ lkkauto.com.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 119151
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

54 Loo Valley Drive Singapore 508269
330 Sin Ming Drive Singapore 575717
45 Pan San Road Singapore 600046

24 Serangoon Road Singapore 556116
7 Loo Valley Drive Singapore 508269
501 Meridian Road Singapore 110121

Date/Time: 12.06.2020 10:22

Page : 1

Team: ARC Repair TP(CFS0)1

JOB CARD Sales Order:

JC NO. 305404148

OWNER

IS

OWNER NO

RESS

(R)

(P)

DUNT CARD NO.

REGN NO

SHC7883L

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

11.06.2020 15:40

DATE TIME IN

YR OF MANU

27.11.2019

TARGET DATE

CHASSIS CODE

KMHC851CVLU180951

COMPLETION DATE/TIME

JOB DESCRIPTION


Accident Date: 11.06.2020

NATURE: 3P 11.06.2020

:/NO

LABOR CODE

DESCRIPTION



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Recognition Slip

Exit Pass

Vehicle No. SHC7883L

JU CHINA LKK

Vehicle No.:

SHC7883L

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection