

ACC. REC. BY:

REF:

CS4/FCI20006356/R1sf3

5402

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 434 2683E

at Workshop m/s YEE KEONH

of 14, RASULAN RD

Insured: FCI

Policy No.

Claims No.

Sum Insured: Excess: TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 42K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

434 2683E

Yr Regn:

2017 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: FIAT DOBLO CARHO MAXI 1.6M c.c 1548

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

20315

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZFA 263000064 30186

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F:

195/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

VOIC

Front

Rear

R/Bal.

5

mm

R/Bal.

4

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

13/06/2020

D.O.I.

17/06/2020

Survey held at

YEE KEONH

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT O/S 2 O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RASUL CONFIRMED L/S \$ 4,700.00/7DAYS WITH HIEW WEI

(\$ 2,733.49/RED - 37%)

Date/Time, File Pass to?

12/08/2020

1) TYPIST

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.S. / L/S \$ 4,700.00

☐ : Prel. Report☒ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL