

ASS. REC BY: Rasul

REF:

CS/CTI18021135/R1qf3


2330

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV
To Inspect Vehicle No: SKU 2632S
at Workshop m/s BORNEO MOTOR
of 2, Pandan Crescent
Insured: CTI
Policy No. DMCVSN1753451801
Claims No. SNM18D05465C02
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 54K
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKU 2632S Yr Regn: 2015 / SEP
Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
Truck / Trailer or _____
Make: TOYOTA CAROLLA ALTIS 1.6 cc 1598
Colour GRY A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA
Sp. Reading 80322 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA
Eng/No: _____
C/No: MR053RE4104537502
Gen. Cond: Good ☒ Fair ☐ Poor ☐ Burnt
Steering: ☒ Worder / ☐ Jammed / ☐ Leaked / ☐ Burnt or
Brake: ☒ Worder / ☐ Jammed / ☐ Leaked / ☐ Burnt or
Modi: Nil ☒ S/Rim / ☐ STD A/Rim or
Tyre Size: F: 205/60R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC ☐ OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 21/11/18 D.O.I. 17/06/2020
Survey held at BORNEO MOTOR
Des. of Damages: Frt ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18/06/20@11.26am	revised to CTI via Merimen.
30/07/20@2.39pm	Rasul finalised with Thomas final fig \$2793.10, 3 days thru email. (Red \$2137.85, 43%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 3

1) 30/07 Typist

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

Report Format: MER-TPLump Sum / L&L: (\$) 2793.10

TOYOTA

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

No : 196700086Z
g No : MR-8500000-9

ESTIMATE

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188
Customer Detail

load "My Toyota SG" app on Playstore or Appstore to access your Toyota account & more!

Account Detail	Account No	Mr Lau Hock Huat 36 Dover Rise #10-06 Singapore 138685 Mobile: 90909299
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	
	Document No 0	
	Document Date 17/06/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R 07/09/2015	SKV2632S	0	55091	72/DS/SKV2632S
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

MR0533REH104537502 12RX527075 60 Thomas Pang W T --/--/---- 0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:CHINA TAIPING INSURANCE TP VEH:GR158B DATE OF ACC:21.11.2018				50 100.00
2	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				180.00
3	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST				122.40
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
5	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				720 1440.00
6	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				590 1180.00
7	1	SPZ061-12021 17 BACK SENSOR 1D4 310A	1.00	159.75		159.75
8	2	S52159-02904 COVER, RR BUMPER	1.00	556.40		556.40
9	3	S52575-02140 RETAINER, RR BUMPER R	1.00	109.30		109.30
10	4	S52576-02140 RETAINER, RR BUMPER L	1.00	109.30		109.30
11	5	S52161-OKO40 PIECE, RR BUMPER	10.00	4.10		41.00
12	6	S52023-02190 REINFORCEMENT, RR	1.00	399.50		399.50
13	7	S81590-02550 LAMP ASSY, RR LH	1.00	353.30		353.30

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 	Please acknowledge receipt of vehicle	<p>Parts</p> <p>Labour 1,728.55</p> <p>Materials 3,202.40</p> <p>Lubrication/Fluid 0.00</p> <p>Others 0.00</p>	<p>4,930.95</p> <p>GST 7.00% 345.17</p> <p>Less 0.00</p> <p>Amount Due 5,276.12</p>

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD
Acknowledged by Repairer
Signature: DATE
PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES. TIME

17/06/2020
09:34

4217064

4217064

VEHICLE NO

SKV2632S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/11/2018 17:21
Date Of Accident	21/11/2018 15:25
Exact Location Of Accident	LOR LIPUT X HOLLAND AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV2632S
Insured/Policyholder	
Name Of Registered Owner	JORGE LAU HOCK HUAT
NRIC No	S1827233D
Email Address	JORGELAU@YAHOO.COM
Mobile Phone No	(LOCAL) +65-90909299
Alternative Phone No	OFFICE-90909299
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA390259
Cover Note Number	
Driver	
Name of Driver	JORGE LAU HOCK HUAT
NRIC No	S1827233D
Date Of Birth	28/09/1967
Occupation	INDOOR
Date Of Driving Pass	12/09/1989
Driving Experience	29 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90909299
Fax Number	
Contact Number	OFFICE-90909299
Email Address	JORGELAU@YAHOO.COM

Address 36 DOVER RISE #10-06
Postcode 138685
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER AS ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number GR158B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver HONG AIGUO
NRIC/Passport Number S2740163E
Contact Number 94577936
Address
Postcode
Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process.
This Form must be completed by the Policyholder and/or the Authorised Driver.
Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



↑
↓
Lor Liput

Describe Circumstances of the Accident

At the red stop light along Lor Liput into Holland Ave, I stopped my car while the traffic light was red.

While waiting, I felt a hard bang from the back of the car.

Upon checking, I saw this blue lorry GR 1583 behind the car.

Driver, one Mr Hong, alight and apologised that he had hit my car.

I told him that I will let my agent check on the damage.

At the agent after checking the car, Mr Hong agrees and ask me to submit a insurance claim on the repair.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



Used 2015 Toyota Corolla Altis X



Merimen e-Claims



YANG

armart.com/used_cars/info.php?ID=858587&DL=3303

▶ Toyota Corolla Altis 1.6A Classic

Overview

Financial

Accessories

Similar

Research

Photos

**ACCENDORE
AUTOLUTION**

Delivering prompt and friendly service

MEMBER OF:



INSURANCE AGENCIES PRL:



MSIG



HL Assurance

Price \$54,800**Depreciation** \$8,750 /yr
View models with similar depre**Reg Date**

16-Sep-2015

(5yrs 2mths 28days COE left)

Mileage 56,018 km (11.8k /yr)**Manufactured** 2015**Road Tax** \$742 /yr**Transmission** Auto**Dereg Value** \$43,520 as of today (change)**OMV** \$17,804**COE** \$57,498**ARF** \$17,804**Engine Cap** 1,598 cc**Power** 90.0 kW (120 bhp)**Curb Weight** 1,205 kg**No. of Owners** 2**Type of Vehicle** Mid-Sized Sedan**Features**1.6L 4 Cylinders Inline Dual VVT-i Engine, CVT Transmission, Keyless Entry/Push Start Function, Auto Headlights.
View specs of the Toyota Corolla Altis (2014-2019)



sg/Ita/vrl/action/enquireRebateByPublicBeforeDeregInput?FUNCTION_ID=F0304009TT

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	233D
Vehicle No.:	SKV26325
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Jun 2020
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1ZRX527075
Chassis No.:	MR053REH104537502
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	07 Sep 2015
First Registration Date:	07 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$19,589.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Sep 2025
PARF Rebate Amount:	\$14,691.00

COE Expiry Date:	06 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,498.00
COE Rebate Amount:	\$30,004.00
Total Rebate Amount:	\$44,695.00

The information contained herein is correct as at 18 Jun 2020

OK

Silver