

ASS. REC. BY:

Steve

REF:

CS/CT120006388/Egf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. DMCVSNA00008232002


Claims No. SNM20D202148C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBL 732J Yr Regn: 30/5/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: PIA 6610 Vespa GTS 300 c.c. 278

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 14521 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZAP M4570 2090 27465

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70-12

R: 130/70-12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. mm L/Bal. mm

D.O.A. 7/6/20 D.O.I. 23/6/20

Survey held at Xin Yun Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Workshop checking price

24/06/20@11.04am revised to Cecilia Low via Merimen. (Labour Only)

03/07/20@4.19pm 2nd revised to Cecilia Low via Merimen.

18/08/20 Steve finalised LS \$4300, 5 days (Red \$10391.40, 71%)

Date/Time, File Pass to?



Preli. Report

1) 19/08 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

\$ + RS. \$

Photos

Others

TOTAL

Report Format: MER-TP

Lump Sum 4300



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

FBL732J VESPA GTS SUPER 300IE ABS/ASR

No	Qty	Parts Description
1	2	Front fork tubes assy whole set X
2	1	Front mugcard / PP
3	1	Fork under bracket ?
4	1	Front rim shaft ?
5	1	Front brake disc X
6	1	Front fender X
7	1	Front fender seal X
8	1	Handle bar / BT
9	1	Hand grip 1 set X
10	1	Handle bar inner bracket ?
11	1	Side mirror left X
10	1	Side mirror right X
11	1	Front signals (LH) / cut
12	1	Front signal panel cover / (RV (Back)
13	1	Front signal lower garnish (Black molding) / cut
14	1	Headlamp X
15	1	Fairing assy 1 set X
16	1	Side cowling inner garnish X
17	1	Centre inner panel X
18	1	Front footrest bracket X
19	1	Front n/s footrest rubber X
20	1	Brake pedal X
21	1	Rear n/s footrest / cut
22	1	Rear n/s footrest bracket X
23	1	Rear taillamp X
24	2	Rear fender (LH) / BR (Engine cover garnish)
25	1	Engine cover metal / PP (LH)
26	1	Swing arm X
27	1	Absorber 1 set (left and right) X
28	1	O/s Garnish Cracked
29	1	Fuel tank cover x1 set metal / PP (RH)
30	1	Rear midshield cover Engine cover LH / cut
30	1	Clutch lever X
31	1	Balancer (LH) / cut
32	1	Exq cover X
33	1	H/P brake broken X

Sub-total parts

Less 10%



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

FBL732J VESPA GTS SUPER 300IE ABS/ASR

No	Qty	Parts Description
----	-----	-------------------

Special Nett Items

1	1	Number plate front and behind 1 set / MC
---	---	------------------------------------------

2	1	Steering cone 1 set / MC
---	---	--------------------------

3	1	Bodysticker / MC
---	---	------------------

Sub-total Special Nett Items

Total parts

Steve (LKK) wil MjL

8322 8813

3 days

L/S

Ry AL sy

23/6/20, 3.00pm

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

FBL732J VESPA GTS SUPER 300IE ABS/ASR

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts, workmanship to dismantle above damaged parts, re-align body structure and damaged consistent to the accident	\$ 800.00	400
2	To putty and spray painting front portion.	\$ 800.00	300
3	To apply anti rust proofing to front left affected area	\$ 120.00	30
4	To check electrical system, wiring and focus front headlamp.	\$ 80.00	30
5	To remove and install front padel, brake padel and absorber	\$ 150.00	50
6	To balance the wheel.	\$ 50.00	20
7	To conduct alignment.	\$ 50.00	20
Total labour :		\$ 2,050.00	

Total parts :

Total labour : _____

Total repair cost : _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 08/06/2020 15:54
Date Of Accident 07/06/2020 04:30
Exact Location Of Accident PASIR RIS DRIVE 06 @BLK 443
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBL732J
Insured/Policyholder
Name Of Registered Owner HELME BIN AHMAD
NRIC No SXXXX089C
Email Address HELMEAHMAD@YAHOO.COM.SG
Mobile Phone No (LOCAL) +65-91541754
Alternative Phone No OTHERS-91541754

Vehicle Particulars

Manufacturer VESPA
Model VESPA GTS SUPER 300 IE ABS/ASR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy NO
Policy Number 5101447460-02
Cover Note Number

Driver

Name of Driver HELME BIN AHMAD
NRIC No SXXXX089C
Date Of Birth 11/06/1974
Occupation OUTDOOR
Date Of Driving Pass 16/06/1995
Driving Experience 24 YEARS AND 11 MONTHS
Gender MALE
Mobile Number +65-91541754
Fax Number
Contact Number OTHERS-91541754
Email Address HELMEAHMAD@YAHOO.COM.SG

Accident Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC KAKI BUKIT (YAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vnl.com.sg

Reporting Centre Personnel's Signature
Name
NRIC/FIN No: 

Accident Sketch Plan

SKETCH PLAN


Parked & Fend Damaged
FBL F32J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


REFER TO POLICE REPORT.
helmeahmad@yahoo.com.sg.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time:


Driver's Signature

(If driver is not the policyholder)

Date & Time

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4 #02-02

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@vac.com.sg

Reporting Centre Personnel's Signature

Name

NRIC/PIN No.

443

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20200607/2005

1 of 3

Report No: T/20200607/2005

Police Station Of Origin:
Pasir Ris N P C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/06/2020 06 05	Vide Report No:	Station Diary No: 6
--------------------------------------------	-----------------	------------------------

Informant's Particulars

Name of Informant: HELME BIN AHMAD		Address: APT BLK 245 TAMPINES STREET 21 #03-317 SINGAPORE 521245	
ID Type / ID No: NRIC NO / S7420089C		Contact No.:	Mobile: 91541754
Nationality: SINGAPORE CITIZEN		Home/Office:	
		Email:	
Sex: Male	Age: 45	Date of Birth: 11/06/1974	Type of Informant: Driver
Race: Malay		Language: English	Institution / School Name:
Occupation: GRAB DRIVER		Driving Licence Information: Class 2B,2A,3	Date of Expiry:

General Information of the Accident

Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 07/06/2020 04.20	Type of Location: Car Park
Location: Along Road 1 PASIR RIS DRIVE 6			
Plk 446 Carpark	Road Surface: Dry	Road Speed Limit:	
Weather: Clear	Traffic Control:	Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBL732J	Motorcycle	PIAGGIO	VESPA GTS SUPER 300 IE ABS/ASR	Grey	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBL732J	NTUC Income Insurance Co-Operative Limited	5101447460-02	30/05/2020	29/05/2021

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20200607/2005

2 of 3

Report No T/20200607/2005

Police Station Of Origin:
Pasir Ris N P C

1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457

Tel No: 1800-5852999

CONTINUATION OF REPORT

Brief Details.

On 07/06/2020 at about 4.17am, I parked my motorcycle FBL732J at the side of the pathway of Blk 446 Pasir Ris 6 carpark. I left my motorcycle there and went to collect my delivery stuffs. I did not park at the motorcycle lot as there were lorry blocking the space.

On the same day at about 4.32am, I went back to my motorcycle and I discovered some damages. There are scratches, broken parts and dented at the left side of my motorcycle. There are scratches and dented at the right rear wheel fender of my motorcycle.

I wish to state that I do not have camera installed. There are CCTV around the vicinity. I observed that no one was injured and I did not observed any vehicle hit my motorcycle.

Accident Sketch Plan



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Pasir Ris N P C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999



T/20200607/2005

3 of 3

Report No: T/20200607/2005

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report
G /
Sgt 1 CHANG ZHEN YONG

Signature Of Informant:

Signature Of Interpreter
Not applicable

Date/Time
07/06/2020 06:05

Officer In Charge Of Case
TP / HRT /
SI NOR AFFENDY BIN JAFFAR
Contact No.. 65476368

Classification Of Case:

Authentication Stamp
NP168

Accident Sketch Plan



T/20200608-2093

1 of 3

Report No. T/20200608-2093

Case Summary Form (CSF For NP168)

Manual NP168 Form Serial No 0

Report Number T/20200608/2093

Vide Report Number T/20200607/2005

Date/Time of Report Made 08/06/2020 22:34

Place Report Lodged Traffic Police

Type of Informant Rider

Name of Informant Helme Bin Ahmad

ID Type / ID No. NRIC NO / S7420089C

Home/Office

Mobile 91541754

Email

Type of Accident Non-Injury / Hit and Run

Drink Drive No

Anyone conveyed by ambulance No

Date/Time of Accident 07/06/2020 04:20

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBL732J	Motorcycle	PIAGGIO	VESPA GTS SUPER 300 IE ABS/ASR	Grey	Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved No	
No. of Pedestrians Injured NIL	Use of Pedestrian Crossing NA