

ASS. REC. BY:

REF: CS3/CTI20006414/Qvf3

Special Instruction:

Surveyor: SUN PIN ASSIGNMENT (Office)From (Person): IRENE TAY of CTI Date/Time: 18-6-20 2.13P.M

Estimated Cost: _____ Bill to: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLM 3808G Insured: SJX 8707Yat Workshop m/s SENG HWEE MOTOR Tel: 67555205of BLK 1018, #01-350 YISHUN INDUSTRIAL PARK APolicy No: _____ Claim No: SNM20D202114

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12-6-2020
(Client's Record)

"WP"

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 18-6-20 2.21 P.M Person Contacted: MR KUEH Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (☒) Estimate
	SLM 3808G - NA/AIG17015173/h4 DOA : 04/08/2017
	SJX 8707Y - ☒
24/6/20	Submit PRS, repair range \$4,000-\$5,000 (4 days)