



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG20004203/Eqf3e2-1

78 SHENTON WAY #09-16

AIG BUILDING

SINGAPORE 079120

ATTN : JEFFREY NG

Date : 24-06-2020



Code : AIG

#### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKM 9605Y	<b>Veh. Inspected</b>	SLX 1002U
<b>Policy No.</b>	2100371940	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	9854223017SG003	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JEFFREY NG	<b>Assign Date</b>	17/06/2020

#### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	KIA CERATO K3	<b>c.c</b>	1591
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	KNAFZ411MJ5761741	<b>Colour</b>	BLUE
<b>Odometer</b>	47856	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

#### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	215/45 R17	PIRELLI	5 mm
<b>L/H Front Tyre</b>	215/45 R17	PIRELLI	5 mm
<b>R/H Rear Tyre</b>	215/45 R17	PIRELLI	5 mm
<b>L/H Rear Tyre</b>	215/45 R17	PIRELLI	5 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

<b>Accident Date</b>	15/03/2020	<b>Inspection Date</b>	18/03/2020
<b>Survey held at</b>	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>6 Working Days</b>
--	-----------------------