



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20006422/Uga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:KITTY

Date : 19-08-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 576E	Veh. Inspected	SKJ 6942J
Policy No.	GA151864	Coverage (\$)	0.00
Claim No.	S0M02PHL	Excess (\$)	0.00
Assign From		Assign Date	18/06/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CAMRY (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053BK4107002453	Colour	SILVER
Odometer	316335	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	NEXEN	6 mm
L/H Front Tyre	215/60 R16	NEXEN	6 mm
R/H Rear Tyre	215/60 R16	NEXEN	6 mm
L/H Rear Tyre	215/60 R16	NEXEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/06/2020	Inspection Date	18/06/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------