

ASS. REC. BY

Surveyor: Amo Quij

REF:

CS3/ASM19009411/1

Gt3-1

Special Instruction:

ASSIGNMENT (Office)

From (Person): weefu.wong

of

ASM(Axx)

Date/Time:

Fri 19/6/2020 1:11 PM

Estimated Cost

Bill to:

OD/TPWS/TPRES/ODRES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLA 330A

Insured:

SKM9568X

at Workshop m/s

Tearnwut Ganey

Tel:

644 2475

of

53 Ubi Ave 1 #01-25

Policy No:

Claim No:

39M010EL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 24/8/2019

Person Contacted:

Barren

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate

paper survey

SLA 330A-XSKM9568X-X30/5/19-Damen call and say car just in todayDismantle: 31/5/2019

ASS. REQ. BY:

GL

REF:

ASM (AXA)

PRS

ASSIGNMENT

From:

Date:

30/5/2019

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLA 330A

at Workshop m/s

Teamwork

of

53 ubi Ave 1 # 01-25

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$168K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLA 330A

Yr Regn:

06 Dec 2012

Type: ☒ Car / ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW M5 4.4 c.c. 4395

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

63607

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBSFV 920 40 DX 95973

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size:

F: 265 / 35 8R 20

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

30-05-19

Survey held at

w/s

5:15 pm

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

3/5/2019

lump sum \$2000 - 3 days (2900; 59%)

RECEIVED 19 JUN 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

100

Transportation:

S + RS: \$

Photos

Others

TOTAL

100

Report Format:

PRS.

Lump Sum / L.B.E. (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)