



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

SOMPO INSURANCE SINGAPORE PL	Ref : CS/SMO20006488/Dyf3s2
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623	Date : 14-08-2020
	Code : SMO



**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	FBR 2004H	<b>Veh. Inspected</b>	FW 9364Z
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2001620/RUC	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GRACE TEO	<b>Assign Date</b>	22/06/2020

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	HONDA WAVE 125S	<b>c.c</b>	125
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2003
<b>Chassis No.</b>	NF125MD0067057	<b>Colour</b>	BLUE
<b>Odometer</b>	-	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	70/90 R17	BRIDGESTONE	2 mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>	90/80 R17	BRIDGESTONE	2 mm
<b>L/H Rear Tyre</b>			mm

**4. Description of Damages**

	THE VEHICLE SUSRTAINED DAMAGES AT THE N/S PORTION, O/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.
--	--

**5. General Information**

<b>Accident Date</b>	16/05/2020	<b>Inspection Date</b>	22/06/2020
<b>Survey held at</b>	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		

**5a. Remarks**

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

**5b. Estimate Days of Repair**

	ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>4 Working Days</b>
--	-------------------------------------	-----------------------