

like

NTUC

COMFORTDELGRO ENGINEERING PTE LTD

Date: 19.06.2020

Time: 15:26:23

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305406044  
REGN NO : SH 9983L  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 13.10.2016  
DATE/TIME IN : 19.06.2020 13:25  
ACCIDENT DATE : 19.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

|                        |                           |    |          |       |        |          |         |
|------------------------|---------------------------|----|----------|-------|--------|----------|---------|
| 0001 04-01-0103-2322-A | I40V3 BUMPER W LIP & FOG  | 1  | 1,052.20 | 20.00 | 841.76 | de ✓     |         |
| 0002 04-01-0103-0638-G | I40VC BRKT ASSY-FR BPR UP | 1  | 22.40    | 20.00 | 17.92  | ny ✓     |         |
| 0003 04-01-0103-0640-G | I40VC BRACKET-FR BUMPER S | 1  | 24.60    | 20.00 | 19.68  | ny ✓     |         |
| 0004 04-01-0101-0111-G | HYUNDAI BUMPER COVER CLIP | 10 | 22.00    | 20.00 | 17.60  | ny ✓     |         |
| 0005 04-01-0103-0573-A | I40VC PANEL-FENDER RH+    | 1  | 663.00   | 20.00 | 530.40 | bt ✓     |         |
| 0006 03-01-0103-0120-G | I40V2 GUARD ASSY-FR WHEEL | 1  | 174.90   | 20.00 | 139.92 | ny ✓     |         |
| 0007 04-01-0103-0658-G | I40VC CAP ASSY-WHEEL HUB  | 1  | 112.50   | 20.00 | 90.00  | ant ✓    | 1499.44 |
| SUB-TOTAL :            |                           |    |          |       |        | 1,657.28 |         |

JOB NATURE

|             |                              |        |     |     |
|-------------|------------------------------|--------|-----|-----|
| 0000 L      | PANEL BEATING                | 650.00 | 420 |     |
| 0001 23-502 | SPRAYPAINT ON AFFECTED AREA  | 450.00 | 400 |     |
| 0002 20-00  | TUFF COAT ON AFFECTED PARTS. | 50.00  | 30  | 930 |
| 0003 20-08  | ADJUST FRONT WHEEL ALIGNMENT | 80.00  | ✓   |     |

1499.44  
930  
2429.44  
454 19.50  
3 days

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 19.06.2020  
Time: 15:26:23  
Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 701045  
ADDRESS: COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305406044  
REGN NO : SH 9983L  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 13.10.2016  
DATE/TIME IN : 19.06.2020 13:2  
ACCIDENT DATE : 19.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,230.00

TOTAL : 2,887.28

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

Tanfilin 97495749  
'WP'

19/6/20 @ 335pm

lumps on  
Body after repair

03 days

Tanfilin @ 11hanta.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: