

ASS. REC. BY:

REF:

AIG/ 2000 6522/KK

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

1-B1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMG 62852

Yr Regn:

11.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Vios E

c.c

1496

Colour:

h. Black

A/C: Insured / Std / NI / NA

Sp. Reading:

30833

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR 2B 231-30601191769

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

3

mm

L/Bal.

6

mm

L/Bal.

3

mm

D.O.A.

18/6/20

D.O.I.

22/6/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/7 @ 1554.02 Callm

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78
SHENTON WAY #07-16
SINGAPORE 079120

Contact : -

Fax No. : 6880 4838

*Not Authorized
Phony B4 pain
3 days*

Estimate : QUOT202006-000503(00)

Date : 22/06/2020

Vehicle No. : SMQ6285L

Make/Model : TOYOTA VIOS 1.5 E (AUTO)

Mileage (km) : 0

Chassis No. : MR2B23F3601191769

Accident Date : 18/06/2020 00:00:00

Claim No. : SLB2356H

Reference : JO202006-0646

Policy No. : 5113975451

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

LIST ITEMS :

1	Rear bumper	1.0	630.10	630.10
2	Rear Bumper clips	6.0	4.21	25.26
3	Rear boot logo	1.0	51.95	51.95
4	Rear Boot emblem - Vios	1.0	48.33	48.33
5	Rear Boot emblem - E	1.0	49.70	49.70
List Total :				805.34
25% Discount S\$				201.32
				604.02

SPECIAL NET :

1	Reverse sensor	1.0	350.00	350.00
SPECIAL NET Total S\$:				350.00

LABOUR :

- To install reverse sensor	1.0	60.00	60.00
-To knock jackout damaged parts, panel beating,welding, align, refix and to renew accident parts	1.0	500.00	500.00
- Spray painting on affected & replace parts	1.0	600.00	600.00
			<u>1,160.00</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: E. & O.E.

Total S\$: 2,114.02

GST 7% S\$: 147.98

Amount Due S\$: 2,262.00

for CITY AUTO PTE LTD