

305406205 Our Job Ref No : ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 25/06/20 **FINALIZATION FORM** LKK Fax: TAUFIKH Attn : Vehicle Reg No. : SH 6907C 19-Jun-20 Date of Accident: The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-NTUC ---SJY6436L 1. The repair job shall bill to: 2. The finalized amount shall be: (a) Spare Parts after List discount (b) Labour Charges **Total for Part-By-Part Repair Cost** (c.) Lumpsum Repair (if applicable) \$1,300.00 Total for Lumpsum repair cost after Less: 20% Final Lumpsum Repair cost \$1,300.00 Estimated normal period for repairs: _____ 2 working days. 3. We shall treat the above amount as Correct and Confirmed if there is no reply from you 4. within 7 working days Thank you for your assistance. We confirm the estimates and 5, finalized amount Signature: Signature TAUFIKH : LIM T S Name Name 25/6/20 62148398 Tel Date 65468156 Fax For Official Use Only Document Confirm By Item Amount Attached Remarks (Signature) Yes or No 1. Rental Rate P/Day YES 2. Loss of Income Paid NO 3. Survey Fees 4. LTA Search Fee \$7.49 Medical Fees (on behalf of driver, if applicable) Overrun Remarks: