

ASS. REC. BY:

REF: CS/CTI20006570/Kqf3

Special Instruction:

Surveyor: KENNETH ASSIGNMENT (Office)From (Person): BEN TANG of CTI Date/Time: 23/6/2020 1:24 PM

Estimated Cost: _____ Bill to: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SGR 4016B Insured: SGS 1359Bat Workshop m/s Auto-body Repair Workshop Tel: 64514958of Blk 176 Sin Ming Drive, #03-11 Sin Ming Autocare BuildingPolicy No: DMPCSNW00037452000 Claim No: SNM20D202195

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19-6-2020
(Client's Record)

"WP"

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 23-6-20 1.49 P.M Person Contacted: NIXON Vehicle IN ☒ OUT

Date/Time	Action/Instruction (☒) Estimate
	SGR 4016B - CC6/AIG15018298/Ahg3q2 DOA : 25/10/2015
	SGS 1359B - CC6/AIG15010868/Kha3q2 DOA : 24/06/2015