



Report No. T/20190114/2100

Police Station Of Origin: Eunos NPP 629 Bedok Reservoir Road #01-1620

SINGAPORE 470629

Tel No: 1800-4439999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/01/2019 15:43			Vide Report No.:	Station Diary No.:		
KUA KA			Address: APT BLK 122C SENGKANG 543122	EAST WAY #09-35 SINGAPORE		
ID Type / ID No.: FIN NO / G7686598T Nationality: MALAYSIAN			Contact No.: Home/Office: Mobile: 83220440 Email:			
Sex: Age: Date of Birth:		Date of Birth: 01/10/1981	Type of Informant:			
Race: Chinese Occupation: SALES MANAGER AT MULTIWAY EMPLOYMENT PTE LTD			Language: English	Institution / School Name:		
			Driving Licence Information: Class: 3	Date of Expiry:		

Type of Accident:	Injury Foreign Vehicle	Drink Drive:	Date/Time of Accident:	Type of Location EXPRESSWAY	
Location:		No	14/01/2019 11:00	- I REGOVIA	
	EXPRESSWAY	. toda Carrace.	IEAR WOODLANDS AV	E 12 EXIT	
Traffic Flow:		Traffic Control:		Traffic Volume:	
		Not Controlled		Heavy	
Type of Collision	711.				

		# 1/2 1/2 1/2				
GBG1695C	Van	TOYOTA	HIACE	Silver	Seriously	0
GBH8691L	Van	TOYOTA	HIACE	Silver	Damaged Slightly	1
GW5853T	Lorry	ISUZU	TFR69H-	D1	Damaged	
JQB737	Car		29(T)	Blue	Seriously Damaged	1
0QD/3/	Car	LEXUS	ES250	White	Seriously Damaged	0



2 of 4

Report No. T/20190114/2100

Police Station Of Origin: Eunos NPP 629 Bedok Reservoir Road #01-1620

SINGAPORE 470629 Tel No: 1800-4439999

	Ular of Day	Use of Pedestrian Crossing: NA			
No. of Pedestrians	s Injured: NIL	Use of Ped	estnan	Cross	ng: NA
Name	TOH TIAN HWEE		ID No.		S7403490Z
Related Vehicle	GBG1695C (Van)		Contact No.		91882875
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disc	harge	NIL	
No. of Days grant	led Medical Leave NIL	Degree of		NIL	
	CONTRACTOR OF THE PERSON OF TH				WAR WILLIAM
Name	MUHAMMAD SUFI SYAFIEE BIN RASULL		ID No.		S9632484G
Related Vehicle	GBH8691L (Van)		Contact No.		98552155
Hospital/Clinic	NIL		Class Driving Licent Expiry	g	Class: NIL Date of Expiry: NIL
Date Treatment	NiL	Date Disc	charge	NIL	
	ted Medical Leave NIL	Degree o			
To. or Day o great					Same of the Contract of the Co
Name	CHEW ENG KENG		ID No.		S1594817E
Related Vehicle	GW5853T (Lorry)		Contact No.		96345878
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
	L.111	Date Disc	_	NIL	
Date Treatment	INB	Date Dist	Cijajus	1 1415	



T/20190114/2100

Report No. T/20190114/2100

3 of 4

Police Station Of Origin: Eunos NPP 629 Bedok Reservoir Road #01-1620 SINGAPORE 470629 Tel No: 1800-4439999

CONTINUATION OF REPORT

Name	KUA KAI LI		ID No).	G7686598T
Related Vehicle	JQB737 (Car)			act No.	83220440
Hospital/Clinic	EASTERN MEDICAL CENTRE				Class: 3 Date of Expiry: NIL
Date Treatment	14/01/2019 Date		Discharge	14/0	/2019
No. of Days granted Medical Leave 02			ee of Injury		

Brief Details.

On 14 January 2019 at about 1100hrs, I was driving my vehicle bearing registration plate number JQB737 along Bukit timah expressway. The road was dry and the traffic was slightly heavy. I was driving at the most left lane alone. Subsequently, before the exit of Woodlands Avenue 12, I was driving slowly. Out of a sudden, I heard a loud braking sound. It was followed by a chain collision involving 4 vehicles including mine. When I was hit by a van behind me, my vehicle pushed forward colliding onto the van in front of me

As such, I alighted from my vehicle to make a check. Here are the vehicles involved:

V1- GW5853T (Lorry)

V2- GBG1695C (Van)

V3- JQB737 (Car)

V4- GBH8691L (Van)

Apparently, earlier while I was moving slowly according to the traffic, V1 had collided onto V2 first and within split seconds V2 hit my vehicle. Subsequently, my vehicle moved forward colliding onto V4. All the drivers involved does not seem to have any injuries on them. Due to the accident, our vehicles sustained the following damages:

V1: Front bumper badly dented

V2: The rear portion of vehicle badly damaged, Front portion of vehicle slightly damaged (dents)

V3: The rear portion badly damaged, Front portion slight dents and scratches, Side bumper misaligned

V4: Slight dents on rear portion with paint marks

Due to the impact of the accident, I feel giddy. As such, I went to the clinic at Eastern Medical Centre and was given 2 days of MC. There was no traffic police or ambulance who came to scene. I got an in car camera. However, I am not sure whether it was recording or not. That's all.





4 of 4

Report No. T/20190114/2100

Police Statlon Of Origin: Eunos NPP 629 Bedok Reservoir Road #01-1620

SINGAPORE 470629 Tel No: 1800-4439999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 AHMAD BIN HASHIM	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 14/01/2019 15:43
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp	