

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHA9517S

DATE: 23. Jun. 2020

MAKE : HYUNDAI

MODEL : IONIQ

DOA: 23. Jun. 2020

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper			\$459.40 <i>Rx</i>
1	Rear Fender - LH			\$1,768.30 <i>Rx</i>
1	Rear Wheel Cover - LH			\$346.40 <i>wt</i>
1	Rear Door - LH			\$1,789.90 <i>Ry</i>
1	Front Door - LH			\$1,797.20 <i>Ry</i>
1	Front Fender - LH			\$490.70 <i>bt</i>
1	Front Wheel Cover - LH			\$346.40 <i>wt</i>
1	Front Bumper - LH			\$418.30 <i>Ry</i>
<b>SUB TOTAL</b>				<b>\$7,416.60</b>
<b>LESS 20%</b>				<b>\$1,483.32</b>
<b>DISCOUNTED TOTAL</b>				<b>\$5,933.28</b>
1	Rear Door APP Sticker			<i>wt</i> \$80.00 <b>Nett</b>
1	Front Door COMFORTDELGRO Sticker			<i>wt</i> \$75.00 <b>Nett</b>
				<b>\$155.00</b>
<b>Labour Charge</b>				
1	Labour Charge			<i>800</i> \$1,200.00
1	Spray Painting Charge			<i>1000</i> \$1,200.00
1	Tuff Kote			<i>40</i> \$100.00
1	Wiring Charge			<i>X</i> \$100.00
2	Transfer of Doors - Frt, Rear			<i>X</i> \$150.00 \$300.00
<b>TOTAL LABOUR</b>				<b>\$2,900.00</b>
<b>ESTIMATE TOTAL</b>				<b>\$8,988.28</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Tanpin 97495747 240pm*  
*2 WP' 24/6/2020*  
*p/p Resurvey before paint*  
*3-4 days*  
*tanpin@lkk.com*

Larry Ng

\* BSD - Blind Spot Detetion \*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**Workshops**

59 Loyang Drive Singapore 508969      24 Senoko Loop Singapore 758156  
 383 Sin Ming Drive Singapore 575717      7 Sungei Kadut Way Singapore 718191  
 45 Pandan Road Singapore 609386      501 Yishun Industrial Park A Singapore 758733  
 320 Upper Selegie Road Singapore 118249

A member of COMFORTDELGRO

Date/Time: 23.06.2020 12:11      Page : 1

Team: ARC Repair TP(CFSO)1

**JOB CARD** Sales Order:

JC NO: 305406618

STOMER  
 CITYCAB PTE LTD  
 STOMER NO: 7010070  
 DRESS 383 SIN MING DRIVE  
 Singapore SINGAPORE 575717  
 65551188

VARs

REGN NO: SHA9517S

MILEAGE

MAKE: HYUNDAI

FUEL E.....1/2.....F

MODEL IONIQ(G2)

DATE/TIME IN 23.06.2020 10:10

YR OF MANU. 17.08.2018

TARGET DATE

CHASSIS CODE KMHC851CVKU106598

COMPLETION DATE/TIME:




COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 23.06.2020  
 NATURE: 3P 23.06.2020

S/NO      ✓ LABOR CODE      DESCRIPTION

CHINA - whole left  
 LFF/



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgment Slip

Exit Pass

Vehicle No. SHA9517S

LARRY

Vehicle No. SHA9517S

LARRY NG

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard