

Our Job Ref No . 305407112

Date : 27. Jun. 2020

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : TAUFIKH

Vehicle Reg No. : SHA8313U

Date of Accident: 24. Jun. 2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC YP8814K

2. The finalized amount shall be:

(a) Spare Parts after List discount \_\_\_\_\_

(b) Labour Charges \_\_\_\_\_

**Total for Part-By-Part Repair Cost** \_\_\_\_\_

(c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_

**Final Lumpsum Repair cost** ~~\$1,750.00~~ \$1700

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Taufikh

Date : 29/6/20

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_