

22/03/2020

CS3/III19009034/R1qf3-1

ASS. REC. BY:

REF:

~~013/III19009034/R1qf3-1~~

Special Instruction:

Summary: RUSU

Derrick Tan

ASSIGNMENT (Office)

29/06/2020

From (Person):

~~Gabriel Wong~~

of

III

Date/Time:

~~22/5/19 @ 3:27pm~~

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 9032

Insured:

SHA 7364D

at Workshop m/s

Kok Wang Car

Tel:

9183 9633

of

1800n lee Street #06-40

Policy No:

MCOM0015

Claim No:

MCT19050261

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/05/2019

CA / REV / REP. / REV 24 HRS

23/5/2019

H.O.D. Endorsement:

Date/Time:

5:32pm @ 22/5/19

Person Contacted:

Mr. Kok

Vehicle ~~IN~~ OUT

Date/Time

Action/Instruction

Ishimoto (X)

SJW 9032 - X

SHA 7364D - X

Dismantle: 24/5/2019 05:21pm

Form REF: III 86592 C
 Date: 23/5/19 ASSIGNMENT COSAP-14: 2020/144

From: SJW 9032J Yr Regn: 2010 APR
 Estimated Cost: 1598
 OD: TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJW 9032J
 at Workshop n/s: Kok weng car
 of: 1 soon lee street #06-46
 Insured: Morning
 Policy No.: MRO532EE106171612
 Claims No.: 147223
 Sum Insured: 19K
 (Client's Record): 19/5/19
 Make of Veh: TOYOTA COROLLA ALTI 1.6A
 (Policy Condition): Grey
 Remark: The veh had commenced its repair at the time of inspection.

Excise: 19/5/19
 Consistent? : Yes or No
 Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 1750 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS 1wp
 Date: 07/07 Person Contacted: TP
 Vehicle: IN / OUT

Veh No: SJW 9032J
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: TOYOTA COROLLA ALTI 1.6A
 Colour: Grey
 Sp. Reading: 147223
 Eng/No: 1598
 C/No: MRO532EE106171612
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / SRim / STD A/Rim or
 Tyre Size: F: 195/55R15
 R: 195/55R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO YOKO or
 Front: 5 mm R/Bal: 5 mm
 L/Bal: 5 mm D.O.I: 16/05/19
 Survey held at: Kok weng
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
0/8 Fnt
 The U/C / Chassis frame / Body Structure affected due to collision.

Submit LS \$1750, 4 days (Red \$2000, 53%)

RECEIVED 07 JUN 2019

Date/Time, File Pass to? ☐ : Prel. Report

1) 07/07 Typist

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / F.D.I. (\$) 1750

Days Of Repair: 4

Resurvey No. of Trip: +

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS, \$

) Photos

) Others

)

TOTAL

| |
|-----|
| 120 |
| 11 |
| 131 |

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|--|---------------|--|---------|---------------|------------|---|
| Main | (Not Notified) Edit Reg | | 22 May 2019 00:00 Edit Adj Rpt | | | | Pending for Survey Report Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

| | | | |
|-----------------------------|---|------------------------|------------------------|
| Insured: | | | |
| Main Claimant: | - | | |
| Vehicle Reg. No.: | SJW9032J | Date of Loss: | 10/05/2019 00:00 - :59 |
| Claim Type: | TP | Policy/Cover Note No.: | |
| Vehicle Reg. No. (Insured): | SHA7364D | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | Kok Wang Car Grooming (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE, 627605 Pioneer - Tel: | | |
| Handling Insurer: | India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 31/05/2019] | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 22 May 2019 3:37 PM
To: Wendy Jiang; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Pooi Chin Han Daniel
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJW9032J[1905-7268(KW)(PD)] (Accident involving SJW9032J and SHA7364D on 10.05.2019)
Attachments: sha7364d_20190522133221.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SJW9032J
III INSURED VEHICLE NO. : SHA7364D
DATE OF LOSS : 10.05.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANT to conduct the pre-repair survey.

This claim is handled by Daniel.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.
Surveyor kindly upload this assignment to Merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Wendy Jiang [mailto:wendy_jiang@rssolomon.com]
Sent: 22 May, 2019 1:55 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Natalie Ng <natalie_ng@rssolomon.com>; Lua Siew Hui <lua_siewhui@rssolomon.com>
Subject: Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJW9032J[1905-7268(KW)(PD)] (Accident involving SJW9032J and SHA7364D on 10.05.2019)

Dear Gabriel,

We refer to your email of even date.

We write to inform that our clients will be appointing their own Surveyors.

In this respect, please arrange your surveyors to contact Mr. Kok of Kok Wang Car Grooming at Mobile No. 9183 9633 for a pre-repair survey of our client's vehicle located at 1 Soon Lee Street #06-40 Pioneer Centre Singapore 627603.

Thank you and Best Regards

Yours sincerely

Wendy Jiang | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

Advocates & Solicitors | Commissioner for Oaths

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e wendy_jiang@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information.

If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system.

Thank you.

On Wed, May 22, 2019 at 1:40 PM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd

- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

| Vehicle Owner Particulars | |
|-------------------------------|--------------------------|
| Owner ID Type: | Company |
| Owner ID: | 8059Z |
| Vehicle Details | |
| Vehicle No.: | SJW9032J |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 24 May 2019 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | COROLLA ALTIS 1.6 AUTO |
| Primary Colour: | Silver |
| Manufacturing Year: | 2010 |
| Engine No.: | 3ZZ4988354 |
| Chassis No.: | MR053ZEE106171612 |
| Maximum Power Output: | 80.0 kW (107 bhp) |
| Open Market Value: | \$16,716.00 |
| Original Registration Date: | 28 Apr 2010 |
| First Registration Date: | 28 Apr 2010 |
| Transfer Count: | 3 |
| Actual ARF Paid: | \$16,716.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 27 Apr 2020 |
| PARF Rebate Amount: | \$8,358.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 27 Apr 2020 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 10 |
| QP Paid: | \$30,000.00 |
| COE Rebate Amount: | \$2,775.00 |
| Total Rebate Amount: | \$11,133.00 |

The information contained herein is correct as at 24 May 2019

OK

19,000
11,133

7867

MSI119062612 / STA INSPECTION PTE LTD - Sin Ming
ENTRY DATE & TIME: 14/05/2019 14:26
SUBMITTED BY: Wong Lip Yong

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 14/05/2019 14:39

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 14/05/2019 14:26
Date Of Accident 10/05/2019 19:05
Exact Location Of Accident 177 SIMS AVE
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJW9032J
Insured/Policyholder
Name Of Registered Owner LA RENTALS PTE LTD
Co Reg No 201838059Z
Email Address JOEL@LAYAUTO.COM
Mobile Phone No
Alternative Phone No OFFICE-93874666

Vehicle Particulars

Manufacturer TOYOTA
Model COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident WORK PURPOSE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage THIRD PARTY
Fleet Policy NO
Policy Number 5106245957
Cover Note Number

Driver

Name of Driver LIM BOON HUAT
NRIC No S7042634Z
Date Of Birth 08/12/1970
Occupation OUTDOOR
Date Of Driving Pass 01/12/1997
Driving Experience 21 YEARS AND 5 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-87660043
Fax Number
Contact Number
EMail Address NOEMAIL

Address BLK 256 KIM KEAT AVE #13-160
SINGAPORE

Postcode 310256

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : NA
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA7364D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver NG BOON KENG

NRIC/Passport Number S1748088Z

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight and was about to turn left along 177 Pine Ave, suddenly car B cut into my lane from the second lane and bang onto my vehicle, causing damage to my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 25.5.19

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 1


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|--|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 10 Jun 2019 12:11 Edit Reg | | 22 May 2019 00:00 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|-----------|---|------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: -, Co. Reg. No.: - | | | | | | | | | |
| Main Claimant: - | | | | | | | | | |
| Vehicle Reg. No.: SJW9032J | | Date of Loss: 10/05/2019 00:00 - :59 [108 Months and 12 Days From LTA Reg Date (Man Yr)] | | | | | | | |
| Claim Type: TP | | Policy/Cover Note No.: | | | | | | | |
| Vehicle Reg. No. (Insured): SHA7364D | | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: Kok Wang Car Grooming (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE, 627605 Pioneer - Tel: | | | | | | | | | |
| Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel] | | | | | | | | | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 31/05/2019] | | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SJW9032J
[SHA7364D]



































TP


-

May 10 2019 12:00AM

[-]

Kok Wang Car Grooming

| | | | | | | | | | | | | |
|------------------|-----------------|--|---------------|--|--|--------------------|--|--|---|-----------|-------------------------------------|--|
| Upload Documents | | | Upload Photos | | | Compose New Letter | | | View | | View in Browser | |
| Photos/Images | | | | | | | | | 3 per page | | <input checked="" type="checkbox"/> | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | Thumbnail | Print | |
| 1 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 2 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 3 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 4 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 5 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 6 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 7 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 8 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 9 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 10 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 11 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 12 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 13 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 14 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 15 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 16 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 17 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 18 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 19 | 06/06/19 18:14 | General View | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 20 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 21 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 22 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 23 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 24 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 25 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 26 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 27 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 28 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 29 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 30 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 31 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 32 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 33 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 34 | 06/06/19 18:14 | Photographs of Damaged Parts | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| Documentation | | | | | | | | | 1 per page | | <input checked="" type="checkbox"/> | |
| No | Finalized On | India International Insurance Pte Ltd (HQ) | | | | | | | | Thumbnail | Print | |
| | | | | | | | | | | | | |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 23/05/19 08:44 | Singapore Accident Statement |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19009034/R1CD3E2

Date: 10/06/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SJW9032J

Insured Vehicle No : SHA7364D

Date of Loss: 10/05/2019

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJW9032J

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4988354

Reg. Date: 28/04/2010 (Man. Year: 2010)

Chassis No: MR053ZEE106171612

Colour: Grey

Odometer: 147223 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 22/05/2019

Date Inspected: 23/05/2019 Inspected At:

Kok Wang Car Grooming (HQ)
1 SOON LEE STREET #06-40 PIONEER
CENTRE
Singapore 627605

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 10 Jun 2019)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJW9032J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >