



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL

Ref: CS3/SMO20006750/Ktf3e2

50 RAFFLES PLACE #05-01/06 SINGAPORE LAND  
TOWERSINGAPORE 048623

Date: 14-07-2020



Code: SMO

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

<b>Insured Veh.</b>	SJK 7856A	<b>Veh. Inspected</b>	GBE 6541R
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2001929	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GRACE TEO	<b>Assign Date</b>	29/06/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	NISSAN NV200 (M)	<b>c.c</b>	1461
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	VSKYBAM20Z0119164	<b>Colour</b>	SILVER
<b>Odometer</b>	42453 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	175/70 R14	WEST LAKE	9 mm
<b>L/H Front Tyre</b>	175/70 R14	WEST LAKE	9 mm
<b>R/H Rear Tyre</b>	175/70 R14	GOODYEAR	9 mm
<b>L/H Rear Tyre</b>	175/70 R14	GOODYEAR	9 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.



### 5. General Information

<b>Accident Date</b>	27/06/2020	<b>Inspect Date / Time</b>	29/06/2020 ( 11:16 AM )
<b>Survey held at</b>	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		

### 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.  
 D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,500.00

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**

Report Ref No. CS3/SMO20006750/Ktf3e2

#### Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.