

ASS. REC. BY:

REF: MSG/20006782/K, f3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

B 58/c

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

12 days

Res.: Yes or No

Lum Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

KENNETH CONFIRMED P/P \$ 18,186.72/12 DAYS WITH BOSS.

(\$ 3,325.60/RED - 15%)

Date/Time, File Pass to?

20/07/2020

1) TYPIST

Date/Time, File Return to?

2)



Prell. Report



Final Report

Days Of Repair:

12

Resurvey No. of Trlp:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S - RES. SI

F. & S.

Others

TOTAL

Veh No:

SMJ 3245J

Yr Regn:

02 19

Type:

M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

Avanza c.c

1591

Colour:

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

49443

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMIT0841CMKU 865473

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD AIR / or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

R/Bal.

7

mm

Rear

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

28/6/2020

D.O.I.

30/6/2020

Survey held at

Des. of Damages:

Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt & o/s body

The U/C / Chassis frame / Body Structure affected due to collision. ✓

Report Format:

Lump Sum (I.B.): P/P \$ 18,186.72