

ASS. REC. BY:

REF:

CS/CT/20006794/R1f3

186F

COE XPRY: 2022/FEB

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKE 2681Pat Workshop m/s MOVAof 100% BUKIT MERAH L3 # 01-04Insured: CTI

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 24K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKE 2681P Yr Regn: 2012 / FEBType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: TOYOTA COROLLA ALTIS 1.6A c.c. 1598Colour: GREEN A/C: Insured / Std / NI / NASp. Reading: 130650 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR053RCE 104129193Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SR / STD A/Rim orTyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or GITI

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 23/06/2020D.O.I. 31/08/2020

Survey held at

MOVA (FAN YUO NH)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair 1 unit - 7K</u>
	<u>Finalised amount of \$ 2,500 / 5 days of lump sum repair is confirmed</u>
	<u>(RED: 1113.77;30%)</u>

Date/Time, File Pass to?

☐ : Prell. ReportDays Of Repair: 5

(1) \_\_\_\_\_

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

(2) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Form: \_\_\_\_\_

Lump Sum / B.B. (%) \_\_\_\_\_



Automotive Pte Ltd

**Main Office:**

Mova Building  
No. 22, Jalan Klang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**

Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: (65) 6272 3892

Fax: (65) 6270 8314

Co. Reg. 198904033G

GST Reg. M2-0088864-2

## Estimate

24/06/2020

**CHINA TAIPING INSURANCE (S) PTE LTD**  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SKE2681P

Veh Model :- TOYOTA COROLLA ALTIS 1.6 AUT

Estimate# :- CK420744

Claim # :-

ACC. Date :- 23/06/20

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
<b>LIST ITEMS :</b>				
1.	FRONT DOOR RH	1	PC	1,207.60
2.	FRONT DOOR STICKER RH	1	PC	69.80
3.	FRONT DOOR PROTECTOR RH	1	PC	89.70
4.	FRONT DOOR PROTECTOR MOULDING RH	1	PC	25.30
5.	CENTER PILLAR RH (REPAIR)	1	PC	1,174.60
6.	REAR DOOR RH	1	PC	69.70
7.	REAR DOOR STICKER RH	1	PC	89.70
8.	REAR DOOR PROTECTOR RH	1	PC	25.30
9.	REAR DOOR PROTECTOR MOULDING RH	1	PC	25.30
10.	ROCKER PANEL GARNISH RH - CHECK	1	PC	
11.	REAR FENDER RH ( REPAIR)	1	PC	
LIST TOTAL S\$				2,751.70
25% DISCOUNT S\$				-687.93
				2,063.77

**LABOUR :**

TO KNOCK & STRAIGHTEN CENTER PILLAR RH, REAR  
FENDER RH. REMOVE & REPLACE ACCIDENT DAMAGED  
PARTS. REALIGN ALL CONNECTION

SPRAY PAINT FRONT DOOR RH, CENTER PILLAR RH,  
ROCKER PANEL GARNISH RH, REAR DOOR RH, REAR  
FENDER RH & DOOR PROTECTORS

REMOVE & REPLACE FRONT & REAR DOOR TRIM BOARD  
MECHANISM AND CHECK LOCKING SYSTEM

RUST PROOF AFFECTED AREAS

LABOUR TOTAL S\$

400 500.00

600 500.00

60 100.00

50.00

1,550.00

LKK Auto Consultants hereby notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by  
Signature:  
Date:

E. & O.E

*[Signature]*

NON-TAX AMOUNT S

AMOUNT S\$ 3,613.77

GST @ 7 % 252.96

AMOUNT DUE S\$ 3,866.73

MOVA AUTOMOTIVE PTE LTD

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT:

Date Of Report	24/06/2020 13:20
Date Of Accident	23/06/2020 19:40
Exact Location Of Accident	CLIVE & DUNLOP (CROSS CONJUNCTION)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE:

Vehicle Registration Number	SKE2681P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LI PENG
NRIC No	SXXXX186F
Email Address	708834560@QQ.COM
Mobile Phone No	(LOCAL) +65-88745266
Alternative Phone No	OFFICE-88745266

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106442876-01
Cover Note Number	

### Driver

Name of Driver	LI PENG
NRIC No	SXXXX186F
Date Of Birth	15/11/1989
Occupation	OUTDOOR
Date Of Driving Pass	29/10/2010
Driving Experience	9 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88745266
Fax Number	
Contact Number	OFFICE-88745266
Email Address	708834560@QQ.COM

Address	8 BOON LAY DRIVE #05-24
Postcode	649928
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : PASSENGERS GENDER: : MALE
Passenger 2	NAME: : PASSENGERS GENDER: : FEMALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN.

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SFJ312B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

2



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

李利

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Sophia

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SKE2681P	ACCIDENT DATE & TIME: 23/06/2020 at 19:40 hrs
CONTACT NUMBER: 88745266	E-MAIL ADDRESS: 708834560@99.com
LOCATION: Clive st & Dunlop (X-junction)	
<p>I was picking up 2 passengers and then driving my vehicle A (SKE2681P) straight along Clive St, when I arrived the junction. Suddenly, vehicle B (SFJ312B) came from Dunlop St and hit onto the right side of the 2 doors of my vehicle.</p> <p>I wish to state that, vehicle B should stop on the stop-line to make sure the main road is clearly then it could move forward, But vehicle did not stop on the stop-line.</p> <p>No one was injured. End.</p>	
<p>NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION</p>	
Please state	
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

[Back to OneMotoring](#)**Inquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 186F

**Vehicle Details**

Vehicle No.: SKE2681P  
Vehicle to be Exported: No  
Intended Deregistration Date: 24 Jun 2020  
Vehicle Make: TOYOTA  
Vehicle Model: COROLLA ALTIS 1.6 AUTO  
Primary Colour: Silver  
Manufacturing Year: 2012  
Engine No.: 1ZRX167238  
Chassis No.: MR053REE104129193  
Maximum Power Output: 90.0 kW (120 bhp)  
Open Market Value: \$14,432.00  
Original Registration Date: 21 Feb 2012  
First Registration Date: 21 Feb 2012  
Transfer Count: 1  
Actual ARF Paid: \$14,432.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 20 Feb 2022  
PARF Rebate Amount: \$7,937.00

**Intended COE Rebate Details**

COE Expiry Date: 20 Feb 2022  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 10  
QP Paid: \$52,392.00  
COE Rebate Amount: \$8,705.00  
**Total Rebate Amount: \$16,642.00**

The information contained herein is correct as at 24 Jun 2020

OK





Merimen e-Claims



Used 2012 Toyota Corolla Altis 1.6



PARF/COE Re

rt.com/used\_cars/info.php?ID=923148&amp;DL=3162

## ► Toyota Corolla Altis 1.6A

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price	\$26,800		
Depreciation ?	\$11,050 /yr View models with similar depre	Reg Date	30-May-2012 (1yr 8mths 28days COE left)
Mileage	135,000 km (16.3k /yr)	Manufactured ?	2012
Road Tax ?	\$742 /yr	Transmission	Auto
Dereg Value ?	\$18,499 as of today (change)	OMV ?	\$15,101
COE ?	\$58,501	ARF ?	\$15,101
Engine Cap	1,598 cc	Power	90.0 kW (120 bhp)
Curb Weight ?	1,195 kg	No. of Owners ?	2
Type of Vehicle	Mid-Sized Sedan		

## Features

Fuel Economical 1.6, 16V DOHC Dual VVT-I Engine, Responsive Auto Transmission, ABS, SRS Airbags, TC. View specs of the Toyota Corolla Altis (2008-2013).

## Accessories

Factory Audio System, Alloy Wheels, Fine Beige Leather Seats. Factory Audio With Reverse Camera, Large Cabin And Boot Space.

Dc