

ALG - JH CLS

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 29.06.2020
Time: 11:24:36
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305408100
REGN NO : SHC 780X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 20.08.2015
DATE/TIME IN : 29.06.2020 08:55
ACCIDENT DATE : 28.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	1,052.20	20.00	841.76	de ✓
0002 04-01-0103-0573-A	I40VC PANEL-FENDER RH+	1	663.00	20.00	530.40	Ry

SUB-TOTAL : 1,372.16

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	500.00	400
0002 17-01	CHECK ALL LIGHTING	30.00	✓

SUB-TOTAL : 830.00

TOTAL : 2,202.16

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanfhir 97495745
-wp
29/6/20 e 25pm
U/S Resurvey after repair
02 days
Tanfhir Elkhantouren