

COMFORTDELORO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SHD6550H
 MAKE : HYUNDAI
 MODEL : I40

DATE: 27. Jun. 2020
 DOA: 26. Jun. 2020

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover			\$1,052.20
1	Front Bumper Side Bracket – RH			\$24.60
1	Front Bumper Top Bracket – RH			\$22.40
10	Front Bumper Clips		\$2.20	\$22.00
1	Headlamp Support Panel			\$907.40
1	Front Fender – RH			\$663.00
1	Front Fender Shield – RH			\$174.90
1	Headlamp – RH			\$1,388.00
1	Front Wheel Cover – RH			\$107.10
SUB TOTAL				\$4,361.60
LESS 20% DISCOUNTED TOTAL				\$872.32
DISCOUNTED TOTAL				\$3,489.28
1	Advertisement – RHF Fender			\$100.00
Labour Charge				
1	Panel Beating			\$600.00
1	Spray Painting Charge			\$500.00
1	Tuff Kote			\$80.00
1	Wiring Charge			\$80.00
TOTAL LABOUR				\$1,260.00
ESTIMATE TOTAL				\$4,849.28

dee
 net
 ?
 net
 x
 R
 x
 x
 de

net
 Nett

420.
 400
 x
 30

LKK Auto Consultants hence notify the Repairer of the following

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Taufik 97495745
 -wp'
 1/5 Resurvey after repair
 Taufik @ Khandan
 29/6/20 @ 310pm
 02-03clips

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by the insurance company.

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:


JC NO.: 305407820

STOMER	REGN NO. SHD6556H	MILEAGE
COMFORT TRANSPORTATION PTE LTD VARS	MAKE : HYUNDAI	FUEL
/MS 7010045	MODEL I-40	E.....1/2.....F
STOMER NO 383 SIN MING DRIVE	YR OF MANU 03.12.2014	DATE/TIME IN 26.06.2020 15:55
DRESS Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMEU061420	TARGET DATE
65508755		COMPLETION DATE/TIME:
(R) (O)		
(P)		
COUNT CARD NO.		

Accident Date: 26.06.2020
NATURE: 3P 26.06.2020 (C)

JOB DESCRIPTION

S/NO	LABOR CODE	DESCRIPTION
✓		CHINA- Right Front LKR



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Identification Slip

Exit Pass

Vehicle No.: SHD6556H

LARRY

Vehicle No.:

SHD6556H

Larry L'...

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard