AIG - (LISUMI)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 30.06.2020
Time: 14:50:29
Page: 1

MPANY : THIRD PARTY'S CLAIMS (CAS)
STOMER: 7010045
DDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO	:	305408283
REGN NO	:	SHD3177M
MILEAGE	:	0000000000
MAKE	:	HYUNDAI
MODEL	:	I-40
DATE OF REGN	:	08.12.2016
DATE/TIME IN	:	30.06.2020 12:40
ACCIDENT DATE	:	30.06.2020

JOB / PARTS DESCRIPTION		QTY	IND UNIT-PRICE	DISC%	AMOUNT	
PART REQUISITION						
0001 04-01-0103-0594-G	I40VC MIRROR ASSY-RR VIEW	1	670.00	20.00	536.00	bw
0002 04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	107.10	20.00	85.68	cb
0003 04-01-0103-0573-G	I40VC PANEL-FENDER RH#	1	663.00	20.00	530.40	KY 621.68

SUB-TOTAL : 1,152.08

JOB NATURE			
0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	500.00	400
0002 17-01	CHECK ALL LIGHTING	50.00	30 810
0003 20-05	RENEW ADVERTISMENT STICKER-FENDER	100.00	

SUB-TOTAL : 950.00

TOTAL : 2,102.08

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE : 30/6/2020

SURVEYOR NAME & SIGNATURE
DATE : Tanghin 97495719

621.68
810
1431.68
4/5 1150
2 days

AIG Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

- WP 30/6/20 @ 3pm
02 days
bumper
Resurvey after repair -
tanghin @ Ithanto an.