

Ag. Chuan

COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.06.2020

REPAIR ESTIMATE

Time: 14:50:29

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305408283
REGN NO : SHD3177M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.12.2016
DATE/TIME IN : 30.06.2020 12:40
ACCIDENT DATE : 30.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0594-G	140VC MIRROR ASSY-RR VIEW	1	670.00	20.00	536.00	pw ✓
0002 04-01-0103-0658-G	140VC CAP ASSY-WHEEL HUB	1	107.10	20.00	85.68	ent ✓
0003 04-01-0103-0573-G	140VC PANEL-FENDER RH#	1	663.00	20.00	530.40	Ry

SUB-TOTAL : 1,152.08

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	500.00	3400
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 20-05	RENEW ADVERTISEMENT STICKER-FENDER	100.00	✓

SUB-TOTAL : 950.00

TOTAL : 2,102.08

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

Insurance Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jia 97495749
- WP 30/6/2020 3pm
02 days
Imp psm
Resurvey after repair -
Tan Jia C Khairi an.

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6290 9755

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 509286
320 Yishun Road Singapore 768132

24 Senoko Loop Singapore 758136
7 Sungai Kadut Way Singapore 729791
501 Yishun Industrial Park A Singapore 768132

Date/Time: 30.06.2020 14:41

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:


JC NO: 305408283

OWNER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755		REGN NO. SHD3177M	MILEAGE
MAKE HYUNDAI		FUEL E.....1/2.....F	
MODEL I-40		DATE/TIME IN 30.06.2020 12:40	
YR OF MANU. 08.12.2016		TARGET DATE	
CHASSIS CODE KMHLB41UMHU096733		COMPLETION DATE/TIME:	

Accident Date: 30.06.2020
NATURE: 3P 30.06.2020/C

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Check-in Slip

Exit Pass

Vehicle No. SHD3177M

JU AIG

Vehicle No.:

SHD3177M

Service Advisor

Signature/Date

Name of Service Advisor

Date

Turned to Service Reception upon collection

To be kept by Security Guard