

Our Job Ref No : 305408800Date : 7. Jul. 2020ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : TAUFIKHVehicle Reg No. : SHD4236UDate of Accident: 2. Jul. 2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO SGL1494E
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$432.12
 - (b) Labour Charges \$1,511.00
 - Total for Part-By-Part Repair Cost** \$1,943.12
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost _____
3. Estimated normal period for repairs: 3 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : Name : Larry NgTel : 6214 8316Fax : 6546 8156Signature : Name : TAUFIKHDate : 8/7/20**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:
