

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/07/2020 14:14
Date Of Accident	20/06/2020 11:55
Exact Location Of Accident	TANGLIN CLUB BASEMENT CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW9655M
Insured/Policyholder	
Name Of Registered Owner	HAGAN SHANE PETER
NRIC No	SXXXX889H
Email Address	HAGEYCARLOS@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-83330115
Alternative Phone No	OFFICE-83330115

Vehicle Particulars

Manufacturer	TOYOTA
Model	PREVIA AERAS-2.4 CVT MR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA445448
Cover Note Number	

Driver

Name of Driver	HAGAN SHANE PETER
NRIC No	SXXXX889H
Date Of Birth	03/03/1967
Occupation	INDOOR
Date Of Driving Pass	24/01/2004
Driving Experience	16 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83330115
Fax Number	
Contact Number	OFFICE-83330115
EEmail Address	HAGEYCARLOS@HOTMAIL.COM

Address	32 JALAN RAJAH #16-01
Postcode	329141
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MOULMEIN NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 101 JALAN RAJAH , POSTCODE: 320101 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2508999 - FAX NO: 63554312
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT. *CCTV ENCLOSED*

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCN2857Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



SKETCH PLAN



A: SLW 9655 M
 B: SCN 2857 Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLEASE REFER TO POLICE REPORT E/20200621/2020
 THE TIME I PARKED MY CAR IS AT 1141 HRS (NOT 1200 HRS)
 AS STATED IN THE POLICE REPORT.

ENCLOSED THE CUB INCIDENT REPORT IDENTIFYING
 THE CULPRIT WHO HIT MY CAR. SCN 2857 Y HIT
 MY CAR WHILE REVERSING.

I REPORTED ONLY NOW AS I NEEDED TIME FOR
 THE CUB TO COMPLETE THEIR INVESTIGATION AND
 PROVIDE ME THE THRD PARTY DETAILS. NO POINT
 FOR ME TO REPORT WITHOUT THE PHOTOS OF THE
 SCENE AND VEHICLE NUMBER.

DECLARATION


I/We declare the foregoing particulars are true in every respect.



 Policyholder's Signature

Date & Time:
 Company Chop (if applicable)

2/7 @ 11:45


Driver's Signature
 (If driver is not the policyholder)
 Date & Time:




 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



E/20200621/2026

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20200621/2026

However he was not able to disclose the details of the vehicle to me without a police report.

As such I am lodging this report for follow up action with Tanglin club and for insurance claims purposes.

Signature Of Officer Recording The Report: E / Sgt 2 JOEL CHOW JUN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 21/06/2020 18:25
Officer In-Charge Of Case: E / Tanglin Police Divisional Investigation Branch / Insp EVANGELINE LIEW Contact No.: 63914801	Classification Of Case:

Authentication Stamp

 <p>SINGAPORE POLICE FORCE SAFEGUARDING EVERY DAY</p> <p style="text-align: right;">SN 80</p> <p style="text-align: center;">SIGNATURE</p>



INCIDENT REPORT FORM

Incident Date 20 th June 2020	Incident 1155hrs	Recorded by Karan/SS	Compiled by Karan/SS	Report No TC 03-20
Reported by (Complainant) Mr Hagan		NRIC / FIN / M'ship No H722	Designation Member	
Address & Contact No c/o The Tanglin Club			Date Of Report 21 st June 2020	Time Of Report 1400hrs
Location Of Incident Main Club Car park Level 1		Nature Of Incident Member Mr Hagan alleged someone brushed against his car right front bumper.		

Brief Facts
 On 21st March 2020 at 1400hrs; member Mr Hagan Membership H722 approached Karan/SS at Main Club car park level 1 and alleged his car had some minor scratches marks on his right front bumper. He alleged may someone hit against his car on the previous day when he came in to Club. Mr Hagan requested security to check CCTV footage at car park and investigate the Incident. Karan/SS acknowledged accordingly.

Investigation & Findings.

CCTV footage and Investigation revealed that;



At 1141hrs as per CCTV footage, Mr Hagen car SLW9655 M arrived at main Club driveway. There isn't any scratches mark on his front right bumper. [Picture 1]

Pg 1/8

INCIDENT REPORT FORM



At 1141hrs as per CCTV footage, Mr Hagen car SLW9655 M arrived at main Club driveway. There isn't any scratches mark on his front right bumper: [Picture 2]




As per CCTV footage at 1141hrs Member Mr Hagen M/sip H722 drove his car SLW 9655 M into Main Club car park and parked his car at Level 1. There isn't any car parked beside on his driver side lot.

Page 2/8


Aaron Chik



INCIDENT REPORT FORM



As per CCTV footage at 1155hrs Member Mr [REDACTED] drove his car SCN 2857 Y into Main Club car park and parked his car at Level 1 beside on member Mr Hagan's car. While reversing his car to park into the lot, [REDACTED] left passenger side brushed against Mr Hagan's car front right bumper. CCTV footage was capture clearly the incident.



As per CCTV footage, upon realized the incident, [REDACTED] quickly turned his front wheels and made second attempt to park properly without any contact with Mr Hagan's car. After he parked his car properly. CCTV Footage capture the second attempt parking.

Pa 3/8

INCIDENT REPORT FORM



As per CCTV footage, at 1156hrs [REDACTED] came out from his car and looking at Mr Hagan's car front right bumper and touched by his right hand and check something. Then he went back and looking at his car left passenger side. CCTV footage was capture his movement when he check Mr Hagen's car. [REDACTED] left carpark at 1354hrs with his wife. [REDACTED] did not report this incident to Club management. [REDACTED]



At 1403hrs a member car parked beside Mr Hagan's car. As per CCTV there isn't any contact with Mr Hagan's car while reversed parked and left car park at 1645hrs.

P34/8

INCIDENT REPORT FORM




At 1624hrs another member car parked beside Mr Hagen's car. As per CCTV there isn't any contact with Mr Hagen's car while reversed parked and left car park at 1644hrs.




As per CCTV footage at 1646hrs another member car parked beside Mr Hagen's car. As per CCTV there isn't any contact with Mr Hagen's car while reversed parked. CCTV footage captured. Mr Hagen left car park at 1758hrs. The said car still parked at the same lot.

Pg 5/8

INCIDENT REPORT FORM




On 21st June 2020 at 1630hrs checked Mr Hagan's car left noticed some minor small scratches on the front right bumper. Checked and confirmed by Karan/SS and Kumar/FOM.




On 21st June 2020 at 1630hrs checked Mr Hagan's car left noticed some minor small scratches on the front right bumper. Checked and confirmed by Karan/SS and Kumar/FOM.

Pg 6/8

INCIDENT REPORT FORM



On 21st June 2020 at 1630hrs checked [redacted] car left passenger side and noticed some minor small scratches on the door frame. Checked and confirmed by Karan/SS and Kumar/FOM.



On 21st June 2020 at 1630hrs checked [redacted] car left passenger side and noticed some minor small scratches on the door frame. Checked and confirmed by Karan/SS and Kumar/FOM.

Pg 7/8



INCIDENT REPORT FORM

Involved members Details as Follows

- Mr Hagan M/ship H722 – H/p 83330115 vehicle registration number SLW 9655 M.
- Mr [REDACTED] – [REDACTED] vehicle registration number SCN 2857 Y.

On 21st June 2020 at 1630hrs Karan/SS and Kumar/FOM spoke to [REDACTED] regards the above Incident. However [REDACTED] denied and refused that the scratches marks on Mr Hagan's car on right front bumper is not cause by his car. He also denied that there isn't scratches marks on his car however there were some minor small scratches marks on his left passenger door frame which check and confirmed by Karan/SS and Kumar/FOM.

As per [REDACTED] he heard the banging sound and he came out from his car after parked his car. He checked Mr Hagan's car however he mentioned that there was no any scratches mark and he decided to leave the car park without inform the Club management.

Karan/SS explained to [REDACTED] that the CCTV footage is captured the whole Incident happened. [REDACTED] acknowledged but still refuse that he is not cause by his car. Karan/SS informed [REDACTED] that CCTV footage recording and Incident report will be submitted to Club management accordingly and he acknowledged.

Mr Hagan was advised to lodge a police report before he claimed the insurance. Mr Hagan acknowledged and informed that he will send an email to Club management to retrieve if his Insurance company needed some relevant document or report related to this Incident.

Conclusion(s)

CCTV footages were saved for management viewed and Incident report was been created and send to Club management.

Membership Department should address this issue.

Pg 8/8

Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo

