



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL Ref : CS/AGI20006963/Ayf3n2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 21-07-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 994Z	Veh. Inspected	SKC 1494E
Policy No.		Coverage (\$)	0.00
Claim No.	C10006634/JM	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	03/07/2020

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN PASSAT CC	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WVWZZZ3CZCE517738	Colour	BLACK
Odometer	84125	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/45 R17	GOODYEAR	6 mm
L/H Front Tyre	235/45 R17	GOODYEAR	6 mm
R/H Rear Tyre	235/45 R17	GOODYEAR	6 mm
L/H Rear Tyre	235/45 R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/07/2020	Inspection Date	06/07/2020
Survey held at	POLYMATH GARAGE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-02 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**