

ASS. REC BY:

REF:

CC4/11120006979/

pa3

5562

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGM 776SD

at Workshop m/s PERFORMANCE

of 303, ALEXANDRA RD

Insured:

111

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

121K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGM 776SD

Yr Regn:

2018, July

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W X1 SDRIVE 18I c.c. 1499

Colour:

BROWN

A/C: Insured / Std / NI / NA

Sp. Reading:

35314

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBAJG120803976200

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: ☒ Nil / ☒ Rim / STD A/Rim or

Tyre Size:

F: 225/50R18

R:

☒ SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

03/07/2020

Rear

R/Bal.

L/Bal.

D.O.I.

07/07/2020

Survey held at

PERFORMANCE

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / L.B.H. ()

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

car 3u

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

04 JUL 2020

ESTIMATE

Estimate No. : b1 55418
Date Estimated : 04/07/2020
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tan Kiang Meng
49 Simei Rise
#05-39

Singapore 528788

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGM7765D	WBAJG120803G76200	30/07/2018	X1 sDrive18i	0

DESCRIPTION	VALUE
To replace front bumper, bonnet, air duct (front wall), bumper support and attachments.	1700 / 5,100.00 front wall - 4250?
Painting front bumper and bonnet.	2102 / 2,326.00
To replace right headlight.	408 / 481.00
To replace left headlight.	408? / 481.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 / 177.00
To supply front emboss number plate.	64 / 83.00
To replace charge air cooler including conduct checks for leak and proper function.	451? / 531.00
To replace air con condenser and air con hose including to vacuum system, top up freon gas and check for leak. (For all models except for 7 series).	852? / 1,003.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 / 177.00
To carry out body cavity preservation. (Per panel).	100 / 118.00
Sundries.	? / 150.00

Total Labour 1: 10,637.00

DESCRIPTION	QTY	PRIC	VALUE
EXPANDING RIVET Na	1	0.80	0.80
CHARGE AIR COOLER ?	1	596.65	596.65

Performance Motors Limited

A Fine Darby Motors Company
Co. Reg No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



Address: 315, Alexandra Road
Fine Darby Performance Centre
Singapore 159941
Fax: 64796603
Date & Time: 07/07/2020 11:45
Surveyor's Name: Rame
Surveyor's Tel: 900 0068
Authorised Date: _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

315, Alexandra Road
Fine Darby Performance Centre
Singapore 159941
Fax: 64796603
Fax: 64796622

Vehicle Consultants hence notify
the Register of the following:
• After Sales
• Motor repair store/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

GST REG. NO : M2 - 0020081-X

ESTIMATE

Acknowledged by: _____
Signature: _____
Date: _____

Estimate No. : b1 55418
Date Estimated : 04/07/2020 5-7 days
Prepared By : Inthiran A/L Thurasamy

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGM7765D	WBAJG120803G76200	30/07/2018	X1 sDrive18i	0

DESCRIPTION	QTY	PRIC	VALUE
BONNET <i>bl</i>	1	1,662.25	1,662.25
FRT CROSSLINK (lower) ?	1	125.00	125.00
IMPACT ABSORBER TOP <i>cm</i>	1	60.15	60.15
FRT BUMPER TOP CARRIER ?	1	375.85	375.85
GRID CENTRE OPEN (BASIS/X LINE) <i>de</i>	1	110.85	110.85
RH FOG LAMP BRACKET ?	1	75.15	75.15
RH ROD ?	1	21.85	21.85
LH COVER GRILLE MIDDLE <i>scu</i>	1	18.95	18.95
RH COVER GRILLE MIDDLE <i>scu</i>	1	18.95	18.95
FRT RH GRILLE SPORT LINE (M) <i>scu</i>	1	121.85	121.85
FRT LH GRILLE (X LINE) X	1	121.85	121.85
FRT RH TOP DEFORMATION ELEMENT <i>cm</i>	1	101.20	101.20
TRIM PANEL AIRDUCT (X LINE) ?	1	225.40	225.40
FRT BUMPER PANEL PRIMED (PDC/PMA) <i>de</i>	1	854.55	854.55
RH OPEN GRID (X LINE PDC) ?	1	95.05	95.05
FRT BUMPER PANEL LOWER SECTION (PDC) <i>de</i>	1	213.65	213.65
RH VERTICAL STRUT ?	1	49.65	49.65
LICENCE PLATE HOLDER ECE <i>cm</i>	1	71.00	71.00
FLAP TOWING EYE PRIMED <i>cm</i>	1	28.90	28.90
BMW PLAQUE WITH ADHESIVE FILM <i>re</i>	1	71.60	71.60
RH HEADLIGHT SUPPORT ARM <i>scu</i>	1	136.45	136.45
SEAL COOLER TOP ?	1	32.15	32.15
RH SUPPORT ?	1	143.60	143.60
CROSSLINK FRONT ?	1	118.60	118.60
FRONT PANEL V STRUT ?	1	116.10	116.10
FRT RH WHEEL ARCH COVER X	1	143.25	143.25
AIR DUCT ?	1	270.55	270.55
HORN HIGH PITCH ?	1	84.95	84.95
WINDSHIELD CLEANING CONTAINER ?	1	134.10	134.10
LH HEADLIGHT LED TECHNOLOGY ?	1	2,684.20	2,684.20
RH HEADLIGHT LED TECHNOLOGY <i>scu</i>	1	2,684.20	2,684.20
RH FOGLAMP ?	1	283.30	283.30
CONDENSER AIR CONDITIONING WITH DRI ?	1	981.90	981.90

Total Parts : 12,834.50



No. of Working Days Recommend _____
Surveyor's E-mail _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
Authorised Date _____
Surveyor's Tel _____
Surveyor's Name _____
Date & Time _____
Excess \$S _____
Regn No. _____
Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Labour 1	:	10,637.00
Parts	:	12,834.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,643.01
Grand Total	:	25,114.51

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/07/2020 15:58
Date Of Accident	03/07/2020 06:45
Exact Location Of Accident	PASIR RIS ROAD JUNCTION (ST 12 & DRIVE 1)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGM7765D
Insured/Policyholder	
Name Of Registered Owner	TAN KIANG MENG
NRIC No	SXXXX556Z
Email Address	ANTHONYTAN01@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98792667
Alternative Phone No	OTHERS-98792667

Vehicle Particulars

Manufacturer	BMW
Model	X1 18I
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	UNAVAILABLE
Cover Note Number	

Driver

Name of Driver	TAN KIANG MENG
NRIC No	SXXXX556Z
Date Of Birth	12/04/1977
Occupation	INDOOR
Date Of Driving Pass	11/12/1998
Driving Experience	21 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98792667
Fax Number	
Contact Number	OTHERS-98792667
EMail Address	ANTHONYTAN01@YAHOO.COM.SG

Address 49 SIMEI RISE #05-39
Postcode 528788
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1 NAME: : ASHLYN TAN YUN XUAN
GENDER: : FEMALE
Passenger 2 NAME: : CEDRIC TAN LI HENG
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC3184Y
Vehicle Make/Model/Colour HYUNDAI COMFORT DELGRO TAXI
Details Of Properties
Vehicle Category TAXI
Name of Driver TAN CHIN TECK
NRIC/Passport Number SXXXX969C
Contact Number 96158324
Address
Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

INDIA INTERNATIONAL INSURANCE PTE LTD
LEFT
1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

3/7/2020

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 3rd July about 0640hrs, I was travelling along Pasir Ris Drive 1. I made a turn into Pasir Ris at 12 when the signal was green, suddenly a taxi SHC3184Y approached from the right on the junction, collided into my vehicle.

- Attached scene video as evidence.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 3/7/2020

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No: 03 Alexander Road
Singapore Police Centre
Singapore 119960

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	556Z
Vehicle No.:	SGM7765D
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jul 2020
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE18I LED NAV
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	F062H844B38B15A
Chassis No.:	WBAJG120803G76200
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$35,811.00
Original Registration Date:	30 Jul 2018
First Registration Date:	30 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$42,136.00

PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jul 2028
PARF Rebate Amount:	\$31,602.00

Intended COE Rebate Details

COE Expiry Date:	29 Jul 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,551.00
COE Rebate Amount:	\$26,233.00
Total Rebate Amount:	\$57,835.00

The information contained herein is correct as at 07 Jul 2020

OK

Used 2018 BMW X1 sDrive18i for

Merimen e-Claims

PARF/COE Re

rt.com/used_cars/info.php?ID=906842&DL=3337

► BMW X1 sDrive18i

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$120,800

Depreciation \$12,530 /yr
View models with similar depre

Reg Date 22-Jun-2018
(7yrs 11mths 14days COE left)

Mileage 22,000 km (10.8k /yr)

Manufactured 2018

Road Tax \$684 /yr

Transmission Auto

Dereg Value \$58,592 as of today (change)

OMV \$35,811

COE \$33,900

ARF \$42,136

Engine Cap 1,499 cc

Power 103.0 kW (138 bhp)

Curb Weight 1,430 kg

No. of Owners 1

Type of Vehicle SUV

Features

Powerful 1.5L Twin Powered Turbocharged 3 Cylinder Engine, Responsive 7 Speed DCT Steptronic Gearbox, Front Wheel Drive, i-Drive, GPS, Bluetooth. View specs of the BMW X1

Accessories

Keyless Entry, Push Start Button, Auto Headlight, Fog Lamps, 18" Sport Rims, Multi Steering Controls, Electric Seats, Memory Seat, Auto Tailgate.