



Your Ref: S0M02GO1

Date: 09th July 2020

Our Ref: CS3/ASM20003122/Eyf3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn : Wong Wee Fu

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: YP 4367K
INSURED VEHICLE: SME 7200M
ACCIDENT DATE: 16/02/2020**

We thank you for your instruction on 06/07/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of YP 4367K from M/s CL Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles YP 4367K.
- c) Final Repair Bill of YP 4367K from M/s Teamwork Garage Pte Ltd.
- d) Colour damaged vehicle photographs of YP 4367K.

Pre-Repair Inspection Date : 03/03/2020 at M/s Teamwork Garage Pte Ltd, 53 Ubi Avenue 1 #01-24, Singapore 408934.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: YP 4367K
Make & Model	: Hino XZU700R-HKFMS3
Year of Registration	: 2016
Chassis Number	: JHHTCS3H70K003142
Engine Capacity	: 4009 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.