

ASS. REC. BY: STEVE

REF: CS 3 / ASM 2000 3022 / ~~4493~~

Special Instruction:

Surveyor: ~~Wong Wee Fu~~ ASSIGNMENT (Office)

From (Person): ~~Jas Tan~~ WONG WEE FU of ASM (AXA)

Date/Time: ~~25/1/2020~~ 6-7-2020

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YP 4367K Insured: SNE 7200M

at Workshop m/s Teamwork Garage Tel: 6844 2475

of BIK 53 Ubi Ave 1 #01-24

Policy No: _____ Claim No: SOMU2601

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 16.2.2020

(Client's Record) CA / REV / REP. / REV 24 HRS "ny" H.O.D. Endorsement: _____

Date/Time: 16/7/2020 1109am Person Contacted: Shu Shan Vehicle-IN (OUT)

Date/Time	Action/Instruction (X) Estimate
	YP 4367K - NA / AA1 1801653E / 2K PUA - 03/07/2020
	SNE 7200M - X
3/3/20	- survey taken
3/3/20	- Ranger taken
1/1	- provide workshop update

ASS. REC. BY: H ANN

REF: ASW (A/R)

PRS

ASSIGNMENT

From: _____ Date: 3/13/2020

Veh No: YP 4367K Yr Regn: 14/110/2018
Type: M.Car / M.Cycle / Bus / Van / (Lorry) / Taxi / Prime Mover /

Estimated Cost: _____

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To inspect Vehicle No: YP 4367K

Make: HINO XZU710K c.c. 4009 cc

at Workshop m/s Teamwork

Colour: white A/C: Insured / Std / NI / NA

of 53 Ubi Ave / #01-3p

Sp. Reading: 177264km T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: JHHTCS3470K003142

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: Inorder / Jammed / Leaked / Burnt or _____

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or _____

Make of Veh: _____

Modi: Nil / S/Rim / STD A/Rim or _____

(Policy Condition)

Tyre Size: F: 7.00-16

R: 7.00-16

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Bal. or Market Value: _____

Front R/Bal. 5) mm L/Asymia R/Rear 4x2 mm

IDAC Accident Rpt: _____ Consistent?: Yes or No

L/Bal. 5) mm L/Bal. 4x2 mm

GIA / PR Seen: _____ Consistent?: Yes or No

D.O.A. 16/2/20 D.O.I. 3/3/20

Est. Repairs: 3 days Res.: Yes or No

Survey held at Teamwork 1144AM

Lum Sum: _____ % 3 Val.: Yes or No

Des. of Damages: Frt / Rear / (O/S) / N/S / UIC / Rooftop or _____

CA / REV / REP. / 24 HRS 47"

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Range → 3-4.5h</u>
	<u>Wkr Days → 3 day</u>
	<u>mv - 39000</u>
	<u>PV - 3582</u>
	<u>NV - 35400</u>

RECEIVED 13 MAR 2020

Date/Time, File Pass to? : Preli. Report : Final Report

Days Of Repair: 3
Resurvey No. of Trip: 1

Date/Time, File Return to? 12/3/20 Typist

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

Survey Fee:	<u>100</u>
Transportation:	_____
Photos:	_____
Others:	_____
TOTAL	<u>100</u>

Rep. Format: PRS
Lump Sum / L.B.J. / ? _____

◀ Service Request Details

Claim

S0M02GO1

Reference

None 

Loss Date

February 16, 2020

Report Date

Feb 25, 2020 9:08:00 AM

Request Date

February 25, 2020

Due Date

March 3, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration

YP4367K

Model

XZU710R-HKFMS3-4.0 D (M)

Service Address

...

Primary Contact/Insured

POH EE HAI

BLK 34 EUNOS CRESCENT, #06-260, 400034, Singapore

83185345

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

7

[New Message](#)

Summer Lee (LKK Auto)

From: TEAMWORK <claims@teamworkgarage.com>
Sent: Tuesday, 25 February, 2020 9:08 AM
To: NIKAM Santosh Pandurang
Cc: TEAMWORK
Subject: [EXTERNAL] RE: OUR REF : 2002-43 // YOUR REF : SME7200M
ACCIDENTINVOLVING SME7200M AND YP4367K
Attachments: GIA REPORT.PDF

Dear Santosh Nikam,

Sorry we have attached the GIA report for vehicle YP4367K.

Thank you and have a nice day.

Regards,

Shu Shan

Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax:6844 2474

From: NIKAM Santosh Pandurang
Sent: Tuesday, 25 February 2020 9:04 AM
To: TEAMWORK
Subject: FW: [EXTERNAL] OUR REF : 2002-43 // YOUR REF : SME7200M ACCIDENTINVOLVING SME7200M AND YP4367K

Hi Sir / Madam,

Kindly confirm the vehicle no. mention in the subject line is different and the attach GIA report is different.

Regards,
Santosh Nikam

From: TEAMWORK [mailto:claims@teamworkgarage.com]
Sent: Monday, February 24, 2020 4:54 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: TEAMWORK <claims@teamworkgarage.com>
Subject: [EXTERNAL] OUR REF : 2002-43 // YOUR REF : SME7200M ACCIDENT INVOLVING SME7200M AND YP4367K

WITHOUT PREJUDICE

OUR REF : 2002-43
YOUR REF : SME7200M

Dear Sir / Madam,
PRE-REPAIR INSPECTION FOR YP4367K
ACCIDENT INVOLVING SME7200M AND YP4367K ON 16.02.2020.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Thank you and have a nice day.

Regards,

Shu Shan
Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax:6844 2474

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Singapore - Externals or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Singapore - Externals or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62563562

To : AXA Insurance Pte Ltd

12/3/2020

Survey details

Date of loss	16-Feb-20
Date of appointment	25-Feb-20
Date of survey	3-Mar-20
Location of survey	Teamwork Garage Pte Ltd

Vehicle Details:

Claim Type:	Third Party
Vehicle number	YP 4367K
Make and Model	HINO XZU700R-HKFMS3
Date of registration	14-Oct-16
Excess	
Market Value	\$39,000
Parf Rebate	\$3,582
Nett Loss	\$35,418

Repair details

Initial Estimate	
------------------	--

Proposed/Revised repair cost:

Parts	
Check item	
Labour	
Total	
Lump Sum(if applicable)	

Number of days of repair	3
--------------------------	---

Remarks:

The estimated repair cost of the damaged vehicle is in the region of \$3,000.00 - \$4,500.00

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	736C
Vehicle Details	
Vehicle No.:	YP4367K
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Mar 2020
Vehicle Make:	HINO
Vehicle Model:	HINO XZU700R-HKFMS3
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	N04CUS28549
Chassis No.:	JHHTCS3H70K003142
Maximum Power Output:	-
Open Market Value:	\$30,342.00
Original Registration Date:	14 Oct 2016
First Registration Date:	14 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$1,518.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Oct 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$5,419.00
COE Rebate Amount:	\$3,582.00
Total Rebate Amount:	\$3,582.00

The information contained herein is correct as at 03 Mar 2020

OK

Fuel Kaki Your Fuel Price Est
Compare and Save To

Connect with Facebook

- HOME
- NEW CARS
- USED CARS
- COMMERCIAL VEH
- RENTAL CARS
- SELL CARS
- MOTOR DIRECTORY

Home > Used Commercial Veh > Hino XZU710R

HINO XZU710R

Handwritten notes: Ute, 16ft, 7000, 35000 + 4614

OVERVIEW GALLERY

Share



Price	\$45,800
Registration Date	14-Oct-2015
COE Remaining	5yrs 7mths 10days
Manufactured	2015
Mileage	100,000 km
No. of Owners	1
Transmission	Manual
Engine Capacity	4,009 cc
Fuel Type	Diesel
COE	\$5,833
Paper Value	\$3,276
Depreciation	\$8,150/year <i>7000</i>
Type	Truck

Singles50 in Singapore

www.singles50.sg



USED VEHICLE SEARCH

hino xzu710r

Category Vehicle Typ

Transmission Engine Cap

Min Price Max Price

Min Depreciation Max Depre

From Reg Year To Reg Yes

Hino 14Pt Truck With 2 Side Sliding Door, 7Pt Height Box. New Paint. Superb Condition Taken Care By Seller. No Other Repair Required. Call Us Now To Arrange For Viewing.

For full set of photos and payment break-down, <https://www.sgcarmart...=850665&DL=3431>

Status: Available | Category: -

Date Posted: 06-Jan-2020 | Date Updated: 20-Feb-2020

Handwritten notes:
 DOA 16ft
 MV - 39000
 PV - 3582
 NV - 35400
 35000 + 4614
 5 year bond
 7000
 7000 - 582

SELLER INFORMATION

Bell Auto Pte Ltd

8 Tuas Avenue 18 (Level 5 & 7) (map)

67457076

RAYMOND

96792154

SP TAN

97686949



VEHICLE TOOLS

- COE Results
- Loan Calc
- Post an Ad
- Road Tax
- Carpark Rates
- Car Insur

SIMILAR VEHICLES



Mitsubishi Fuso Canter FECK1
 04-Feb-2015
 \$45,800



Mitsubishi Fuso Canter FEB71
 04-Sep-2014
 \$49,800



Isuzu NHR85A Tipper (COE till 08/2028)
 06-Aug-2008
 \$49,800



Isuzu NNR85
 12-Jan-2017
 \$50,000

Meet your mature soulr

www.singles50.sg

LIFESTYLE

- Food & Beverage
- Health Ci
- Home Needs
- IT Produ
- Men's Fashion
- Men's Ho

Top Team Management Tool

Project & Task Management Tool that Grows w/ Your Team. Free Trial. Write

Hino XZU700R

2015

Transmission

Truck

* Exempt A.S.

* Available Used Vehicles

X

Home » Used Cars » United Overseas Bank Limited » Hino XZU700R

Hino XZU700R

[Overview](#) | [Accessories](#) | [Similar](#) | [Research](#) | [Photos](#) | [Map](#)

We do not warrant the accuracy of this info.
The bidder is expected to do his/her due diligence checks before bidding.

Price	N.A	Lifespan	03-Aug-2037
Depreciation	N.A	Reg Date	04-Aug-2017 (7yrs 5mths COE left)
Auction closing	27th Mar 2019 at 11:00 PM		
Mileage	N.A.	Manufactured	2017
Road Tax	N.A.	Transmission	Manual
Dereg Value	N.A.	OMV	\$38,267
COE	\$16,938	ARF	\$1,914
Engine Cap	4,009 cc	No. of Owners	1
Curb Weight	2,460 kg		
Type of Vehicle	Truck		

Features

SRS Airbags, ABS.

Accessories

CD Player, Fog Lamp.

Description

With Key, This Vehicle is Non GST Chargeable. Kindly Download The Non GST Chargeable Tender Form At This Link: <https://goo.gl/F6nT89>

Category

Auction Vehicle

Status

Expired

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 23-Mar-2019 | Last updated on: 15-May-2019

Tags: Hino XZU700R, 2017 Hino XZU700R, Hino, XZU700R.

Recommended for you



Increase for Cat A and B while Cat E falls



Gojek to introduce \$0.70 surcharge



Vehicle sales and transfers to go online



218i Gran Coupe: BMW's compact fighter



8 Top European Car specialists in East



10 Best aircon repair & servicing experts

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/02/2020 12:03
Date Of Accident	16/02/2020 19:45
Exact Location Of Accident	ALONG PAYA LEBAR ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP4367K
Insured/Policyholder	
Name Of Registered Owner	UNI-TAT ICE & MARKETING PTE LTD
Co Reg No	1XXXXX736C
Email Address	EARL@POLARMART.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-67448484

Vehicle Particulars

Manufacturer	HINO
Model	XZU710R-HKFMS3-4.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	2019-V0105894-VCV-R001
Cover Note Number	14/10/2019 TO 13/10/2020

Driver

Name of Driver	HE JINGZHI
NRIC No	GXXXX187X
Date Of Birth	15/07/1989
Occupation	OUTDOOR
Date Of Driving Pass	29/11/2017
Driving Experience	2 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96657706
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address 51 UBI AVENUE 1, #01-26, PAYA, UBI INDUSTRIAL PARK, SINGAPORE
408933

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SME7200M *Hyundai elantra 2015*

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1) Please report **correctly** on the details of the accident to speed up the claims process.
- 2) This form must be **completed by the policy holder and/or the authorised driver.**
- 3) Information provided must be as **truthful and accurate as possible.** Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
- 4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5) **Any false reporting may be referred to the police for investigation.**
- 6) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7) By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8) **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of:
 - (i) Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigations the accident and/or my claims;
 - (iii) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) Administering my claims (including the mailing of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelops/mail packages); and/or
 - (v) Complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - (i) To all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposed stated, or
 - (ii) For complying with requirements under my regulations, laws or court orders.



Policyholder's Signature
Date & Time:

何#志


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling straight along Raya Lebar Road at the third lane.

Vehicle B which was at the second lane suddenly cut into my lane and collided onto right side of my vehicle.

.....*for company vehicle only*.....
 I _____ is the _____ of
 company _____ and im using the vehicle
 _____ for work /private purpose .

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

何#志

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9507198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD		Ref: CS3/ASM20003122/Hyf3e2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE		Date: 19-03-2020	
068811		Code: ASM	
ATTN : JAS TAN			
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SME 7200M	Veh. Inspected	YP 4367K
Policy No.		Coverage (\$)	0.00
Claim No.	S0M02GO1	Excess (\$)	0.00
Assign From	JAS TAN	Assign Date	25/02/2020
2. Vehicle Particulars & Condition			
Make & Model	HINO XZU700R	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JHHTCS3H70K003142	Colour	WHITE
Odometer	197254 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	7.00-16	CASUMINA	5 mm
L/H Front Tyre	7.00-16	CASUMINA	5 mm
R/H Rear Tyre	7.00-16 (D)	KENDA	4/4 mm
L/H Rear Tyre	7.00-16 (D)	KENDA	4/4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
5. General information			
Accident Date	16/02/2020	Inspect Date / Time	03/03/2020 (11:44 AM)
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,500			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

Report Ref No. CS3/ASM20003122/Hyf3e2

Inspected By



LEE HOCK ANN

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, Minst(AEA), MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.