

(08/11/13) wef

ASS. REC. BY: Maria

REF:

CC6/11120007000/453

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

FBE 5013 E
Enofia

at Workshop m/s

of

Insured:

SKN 206X

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

47800

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

7580

Vehicle: IN / OUT

Date:

Person Contacted:

mt 3518

Veh No:

FBE 5013 E

Yr Regn:

ST 10

Type: M.Car / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha RX 2

c.c

133

Colour

Yellow

A/C:

Insured / Std / NI / NA

Sp.Reading

90227

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

PMYSPV100A0031625

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or affected

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

R:

80-90-18

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

20/6/20

D.O.I.

6/7/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

PM, NIS 304

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

00 5.5.2030 LTA 4282

3/8/20 4/5 1900 confirmed with MR 700

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Dinie Firdaus Bin Jamil

Accident Date : 20-Jun-20

Vehicle No : FBE5013E

Vehicle Model : Yamaha RXZ

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 65.00 ✓
2	Fork inner tubes	\$ 210.00 ✓
2	Fork outer tubes	\$ 220.00 ✓
1	Fork under bracket	\$ 145.00 ✓
1	Front sport rim	\$ 250.00 ✓
1	Front rim shaft	\$ 38.00 ✓
1	Top cowl	\$ 85.00 ✓
1	Windshield	\$ 32.00 ✓
1	Lamp assy	\$ 50.00 ✓
1	Headlamp	\$ 70.00 ✓
2	Front signals	\$ 80.00 ✓
1	Handle-bar - L/H	\$ 68.00 ✓
1	Handle-bar end	\$ 18.00 ✓
1	Clutch lever	\$ 25.00 ✓
1	Meter assy	\$ 480.00 ✓
1	Front footrest - L/H	\$ 32.00 ✓
1	Front footrest bracket - L/H	\$ 55.00 X
1	Gear pedal	\$ 32.00 ✓
1	Rear footrest - L/H	\$ 28.00 X
1	Rear tailboard - L/H	\$ 70.00 X
1	Mirror assy	\$ 40.00 ✓
1	Fork top holder	\$ 90.00 ✓
1	Key lock assy	\$ 160.00 X
		\$ 2,343.00
	Less 10%	\$ 234.30
		\$ 2,108.70

Special Net Items

1	Number plate (1 set)	\$ 28.00 10
2	Fork oils	\$ 30.00 ✓
2	Fork oil seals	\$ 56.00 ✓
1	Steering cone (1 set)	\$ 75.00 ✓
1	E.R.P. IU	\$ 175.00 X
1	Front tyre	\$ 100.00 50%
1	Horn	\$ 20.00 ✓
		\$ 484.00

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Dinie Firdaus Bin Jamil

Accident Date : 20-Jun-20

Vehicle No : FBE5013E


Vehicle Model : Yamaha RXZ

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service	\$ 35 60.00
2	To ckeck wiring and reset headlamp focusing	\$ 11 80.00 X
3	To provide labour	\$ 300 380.00
		<u>\$ 520.00</u>
Grand Total		<u>\$ 3,112.70</u>

Singapore Dollars: Three Thousand One Hundred Twelve and Cents: Seventy only

2403
192


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: