



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63885592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/07/2020
 User ID : BoonChewTay

Section A - Accident Details

Registration Number	SG5948X
Case Reference Number	BUS/06/20/1053
Registration Date	14/8/2018
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95 MAN E6
Name of Driver	Leong Kok Yew
Type of Accident	Side Swipe
Accident Date and Time	30/6/2020 7:00 PM
Accident Reported Date and Time	30/6/2020 9:45 PM
Surveyor Required?	No
Surveyed by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG5948X-RIGHT REAR PORTION GBJ2195G (TP) INSURED WITH Alfa
Prepared Date and Time	3/7/2020 2:10 PM
Chassis Number	WMAA95ZZ1JF007405
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$772.00	\$0.00
Total Spare Part Cost	\$3,563.72	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$5,925.72	\$0.00
Temp Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	03/07/2020 3:08 PM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 03/07/2020

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	1060
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$772.00	602
Total Spray Painting & Panel Beating	\$772.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
013482	Body	124-2-2-009-012	O/S FRP REAR LAMP	1.00	\$975.00	10.00	\$877.50	Replace	/ CRAFU
010298	VE	88-25225-6039	LAMP STOP LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace	/ CRA
010299	VE	88-25320-6008	LAMP INDICATOR LED (MAN BUS)	1.00	\$1,274.10	10.00	\$1,146.69	Replace	/ CRA
012635	VE		REAR LAMP BULB (A95 MAN)	1.00	\$245.00	10.00	\$220.50	Replace	/ CRA
012636	VE		REVERSE LAMP BULB (A95 MAN)	1.00	\$235.00	10.00	\$211.50	Replace	/ CRA
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	/ MA
			STICKER 60KM/H	1.00	\$5.00	0.00	\$5.00	Replace	/ AEC
Total					\$3,950.80		\$3,563.72		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Sun Pin (L1111)
TP with my program
03/07/2020

Repair dy - 3 days
L/S

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: