COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref

305409383

Date

06072000

Time of Fax:

Via Fax

Your Insured:

Date of Acc

Buail Cli 1644R

04072000

Fax no. 6546 8156

Attn: Motor Claims Department

Dear Sirs

Aig Asia

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident ___

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

Lim Kwok Eng

Tel: 6214 8316 or HP: 9824 0811

Jumani Bin Masudin

Tel: 6214 8315 or HP: 9635 5305

Lim Tien Siong

Tel: 6214 8398 or HP: 9635 8546

Chiang Liat Choon

Tel: 6214 8314 or HP: 9296 6006

Larry Ng Nyuk Phin

Tel: 6214 8315 or HP: 9230 2824

Fauzy Bin Mokhtar

Tel: 6214 8319 or HP: 8125 9176

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Siong

for Vice President Crash Repairs & Claims Recovery

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Updated 11 Feb 2020

P1/2

DATE:

6-Jul-20

INSURANCE: AIG ASIA

MODEL:

Hyundai i40 (Rear)

MVA: LIM TS

VEHICLE NO.: SHB4171H

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Bootlid	1		\$2,174.90
	Bootlid Hinge (LH/RH)	2	\$142.30	284.60
	Bootlid Lock Upper	1		\$114.90
	Bootlid Lock Lower	1		\$31.70
	Bootlid 'H' Emblem	1		\$28.70
	Bootlid CRDI Plate	1		\$27.90
	Bootlid I40 Emblem	1		\$27.90
	Bootlid Lamp (LH/RH)	2	\$565.60	\$1,131.20
	Rear Bumper	1		\$1,106.00
	Rear Bumper Reinforcement Bracket	2	\$80.30	\$160.60
	Rear Bumper Reinforcement	1 1		\$428.40
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00
	Rear Bumper Reinforcement Bracket RH/LH	2	\$35.60	\$71.20
	Rear Bumper Sponge	1		\$119.50
	Rear Bumper Under Cover	1		\$228.00
	Rear Bumper Reflector RH/ LH	2	\$32.00	\$64.00
	Tail Lamp (LH/RH)	2	\$697.80	\$1,395.60
	Rear Panel	1	Ψουου	\$526.70
	Rear Panel Garnish	1		\$57.70
1	Rear Panel Lower Panel	1		\$495.50
	Spare Tyre Holder	1		\$248.00
	Rear Towing Hook	1 1		\$94.60
	Exhaust Silencer RH/LH	2	\$967.70	\$1,935.40
	SUB TOTAL		-	\$10,775.00
	LESS 20%			\$2,155.00
	DISCOUNTED TOTAL			\$8,620.00
	BootLid ComfortDelGro	1		\$30.00
- 1	BootlLid 65521111	1		\$30.00
- 1	BootLid APPS	1	1	\$40.00
ı	Rear Bumper MAT	1		\$50.00
1	Reverse Sensor	1		\$135.70
	NETT TOTAL			\$285.70
	TOTAL SPARE PARTS			\$8,905.70
				Vojodano

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
			SHB4171H	P2/2
	Labour Charge			
	Panel Beating			\$900.00
	Spray Painting Charge			\$1,000.00
	Wiring Charge			\$50.00
	Tuff Kote		1	\$100.00
	Remove/Refix Reverse Sensor		l	\$120.00
	Remove/Refix Exhaust Pipe			\$150.00
	TOTAL LABOUR			\$2,320.00
	ESTIMATE TOTAL			\$11,225.70

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Occupation

Gender

Date Of Driving Pass

Driving Experience

Mobile Number

Fax Number
Contact Number
EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3, Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6, This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.				
The Tay of the County	ACCIDENT STATEMENT			
Date Of Report	06/07/2020 10:21			
Date Of Accident	04/07/2020 15:30			
Exact Location Of Accident	ECP EXIT 10A TOWARDS MARINE PARADE FLYOVER			
Country/State of Loss	SINGAPORE			
	DETAILS OF OWN VEHICLE			
Vehicle Registration Number	SHB4171H			
Insured/Policyholder				
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD			
Co Reg No	1XXXXX821R			
Email Address	FLEETSAFETY@CDGETAXI.COM.SG			
Mobile Phone No				
Alternative Phone No	OFFICE-65508768			
Vehicle Particulars				
Manufacturer	HYUNDAI			
Model	140			
Exact Purpose for which vehicle was being used at time of accident				
Are you claiming under your own insurance policy for repair to your vehicle?	NO			
If No, Please state action to be taken	THIRD PARTY			
Vehicle Category	TAXI			
Insurance Company				
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD			
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT			
Fleet Policy	YES			
Policy Number	MCOM0015			
Cover Note Number				
Driver Transfer of the Control of th				
Name of Driver	YAP BOON OOI			
NRIC No	SXXXX437J			
Date Of Birth	28/05/1971			

AHWEIYBO528@GMAIL.COM

28 YEARS AND 10 MONTHS

(LOCAL) +65-90281813

OUTDOOR

26/08/1991

MALE

Address BLK 502 JELAPANG ROAD

#17-388

Postcode 670502

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OTHER - TAXI DRIVERTAXI DRIVER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO 4

Number of Passengers (Including Driver)

Passenger 1

NAME:

. 9

GENDER: MALE

Passenger 2

NAME:

GENDER:

. .

: FEMALE

: FEMALE

Passenger 3

NAME:

\$ X

GENDER:

Details of Police Action

Was the accident reported to the police?

NO

If Yes.Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

1043

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLL1644E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NG YEW KEN DESMOND

NRIC/Passport Number

Contact Number

97515015

Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

YAP BOON OOI

Approximate Age

Injuries Sustain

BACK AND NECK

Injured person in which vehicle?

SHB4171H

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan Pg. 1

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information setout in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outlisde of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared/disclosed:
 - to all Insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD

CO. REG. NO. 199303821R

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)

Date & Time:

Olivia Wer


Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

n 6 JUL 2020

Page 4 of 20

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A PROPERTY OF THE PROPERTY OF
On the Altlagae @ 1530 me, I was driving along ECP EXITION towards Marine Paradle Flyever— Chirection with 3 passenger on board my taxi.
I Slop before the Slopping line when Suddenly there's an impact from behind my taxi. So I step at to check and found a vehicle of QLL 1644 E front portion had collinded anto my taxi rear portion. [Cett Slight book and reak pain after the Impact and will consult abotor later.

CLARATION

e declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION TELTO CO. REG. NO. 199303821R

:yholder's Signature

Mr Champs and Art of the Fig.

& Time:

Drive's Chature
(If drive' is not the policyholder)
Date & Time:

10 9

Olivia Wendy

Reporting Centre Personne & Silliture Name:

NRIC/FIN No .:

0 ⁸ 5 0 1,000