

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SHC 23754 Yr Regn: Dec / 2019  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Hyundai Ionig c.c. 1580  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp.Reading: 58925 T/Radio: Insured / Std / NI / NA  
 Eng/No: G4LEK4409555  
 C/No: KMHC851CVLU190055  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: in order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: in order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 195/65 R15  
 R: — " —

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Michelin

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 8 1/2 days Res.: Yes or No  
 Lum Sum: 71P % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Front Rear  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 04/07/2020 D.O.I. 07/08/2020  
 Survey held at Ex Frost Sin Ming  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
O/S Front  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MSG SLK 1295J
28/12/2020	Final 71P 13,156.92 with 8 days of work <del>117.24</del> (\$17048.39 Red - 56%)

Date/Time, File Pass to? \_\_\_\_\_  
 1) 28/12/20 TYATA  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format : \_\_\_\_\_  
 Lump Sum / L.S.I. (\$) 13,156.92 PIP

Days Of Repair: 8  
 Resurvey No. of Trip: 2  
 Add Fee:  Site Insp (\$) \_\_\_\_\_  
 Interview (\$) \_\_\_\_\_  
 Tech. Invs (\$) \_\_\_\_\_  
 Weekend (\$) \_\_\_\_\_

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S+RS SI \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/07/2020 10:35
Date Of Accident	04/07/2020 22:30
Exact Location Of Accident	SYED ALWI RD X TOWNSHEND RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC2375U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@CDGETAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	PNG YAP KIM CHUA
NRIC No	SXXXX692F
Date Of Birth	15/01/1958
Occupation	OUTDOOR
Date Of Driving Pass	28/01/1977
Driving Experience	43 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98179348
Fax Number	
Contact Number	
EMail Address	PNGYAPKC@GMAIL.COM

Address BLK 2 FLORA DRIVE  
#03-40  
Postcode 507025  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions RAINING  
Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

REFER ATTACHED \* TYPE OF ACCIDENT :- HEAD TO SIDE

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons: -  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLK1295J  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver HAN HOW HENG  
NRIC/Passport Number  
Contact Number 88752361  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage FRONT LH  
No. Of Passenger (Including Driver)

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 06.07.2020  
@ 09:15 hrs

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



A - SHC 2375U  
B - SLK 1295J

Along Syed Alwi Road x Townshend Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 04.07.2020 at about 21:15 hours I was travelling along Syed Alwi
Road x Townshend Road with no passenger onboard .
While travelling straight , suddenly veh B ( SLK 1295J ) - dash out
from my right without giving to collided into my taxi A - Front Right
Portion .
No injury in this accident .
I have company video and photos at scene to support my claims .
Veh B ( SLK 1295J ) - Mr Han How Heng H/P : 8875 2361

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 06.07.2020  
@ 09:15 hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 6-Jul-20

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC2375U

INSURANCE: MSIG

DESCRIPTION	QTY	Unit Price	Amount	
Bonnet <i>HW</i>	1	\$ 2,253.80	\$ 2,253.80	X
Bonnet Hinge (RH) <i>HW</i>	1	\$ 118.70	\$ 118.70	X
Bonnet Insulator Clips <i>HW</i>	1	\$ 15.00	\$ 15.00	X
Radiator Grille NEW MODEL <i>2 HW</i>	1	\$ 1,568.60	\$ 1,568.60	X
Flap Assy Active Air Upper, (RH) <i>HW</i>	1	\$ 824.60	\$ 824.60	X
Front Bumper Cover <i>form</i>	1	\$ 418.30	\$ 418.30	L
Front Bumper Moulding Centre Upper <i>2 HW out</i>	1	\$ 368.50	\$ 368.50	<del>X</del>
Front Bumper Bracket Top (RH) <i>HW</i>	1	\$ 35.00	\$ 35.00	X
Front Bumper Bracket (RH) <i>src</i>	1	\$ 28.00	\$ 28.00	X
Front Bumper Retainer Mounting (RH) <i>src</i>	1	\$ 65.30	\$ 65.30	X
Front Bumper Clips 10 pcs <i>HW</i>	1	\$ 25.00	\$ 25.00	L
Front Bumper Grille (RH) <i>distorted</i>	1	\$ 186.90	\$ 186.90	L
Front bumper air duct (RH) <i>2 HW</i>	1	\$ 153.80	\$ 153.80	<del>X</del>
Day Light, RH <i>2 mounting broken</i>	1	\$ 642.50	\$ 642.50	<del>X</del>
Day Light Wire, RH <i>HW</i>	1	\$ 585.50	\$ 585.50	<del>X</del>
Headlamp Support Panel Assy <i>2 broken</i>	1	\$ 949.30	\$ 949.30	<del>X</del>
Headlamp(RH) <i>2 mounting broken</i> <span style="float: right;">1198.80</span>	1	\$ <del>3,987.30</del>	\$ 3,987.30	<del>X</del>
Radiator Inverter <i>HW</i>	1	\$ 884.80	\$ 884.80	X
Radiator <i>HW</i>	1	\$ 710.50	\$ 710.50	X
COOLANT <i>HW</i>	1	\$ 45.00	\$ 45.00	X
Radiator fan blower motor assy <i>HW</i>	1	\$ 1,226.60	\$ 1,226.60	X
Radiator Air Guard (RH) <i>HW</i>	1	\$ 76.40	\$ 76.40	X
Frt Pillar Upper Cover - outer (RH) <i>HW</i>	1	\$ 89.60	\$ 89.60	X
Front Fender(RH) <i>src</i>	1	\$ 490.70	\$ 490.70	L
Front Fender Apron Panel (RH) <i>HW</i>	1	\$ 756.20	\$ 756.20	X
Front Fender Apron Panel Upper(RH) <i>HW</i>	1	\$ 229.60	\$ 229.60	X
Front Fender Shield (RH) <i>distorted</i>	1	\$ 164.70	\$ 164.70	L
Aircon Condenser <i>HW</i>	1	\$ 663.60	\$ 663.60	X
Frt Door(RH) <i>repair Bt (distorted)</i>	1	\$ 1,797.20	\$ 1,797.20	<del>X</del>
Frt Door Rubber <i>HW</i>	1	\$ 250.00	\$ 250.00	X
Front Door Hinge Upper (RH) <i>HW</i>	1	\$ 165.76	\$ 165.76	X
Front Door Hinge Lower (RH) <i>HW</i>	1	\$ 153.70	\$ 153.70	X
Front Door Check (RH) <i>HW</i>	1	\$ 72.98	\$ 72.98	X
speaker <i>HW</i>	1	\$ 256.10	\$ 256.10	X
Front Wheel Rim (RH) <i>2 distorted</i>	1	\$ 1,124.20	\$ 1,124.20	<del>X</del>
Front Wheel Hub Cap and hub assy (RH) <i>end</i>	1	\$ 678.50	\$ 678.50	L
Front Shock Absorber(Assy)(RH) <i>2 1st</i>	1	\$ 372.50	\$ 372.50	<del>X</del>
Front Shock Absorber Mounting (RH) <i>HW</i>	1	\$ 206.90	\$ 206.90	X
Front Drive Shaft (RH) <i>HW distorted</i>	1	\$ 1,136.70	\$ 1,136.70	<del>X</del>
Front drive shaft extension RH <i>HW</i>	1	\$ 1,125.80	\$ 1,125.80	X
Rack & Pinion Assy <i>HW Dam</i>	1	\$ 1,087.40	\$ 1,087.40	<del>X</del>
STG Tie Rod <i>2 distorted</i>	1	\$ 125.60	\$ 125.60	<del>X</del>

STG Tie End <i>to destination</i>	1	\$ 94.70	\$ 94.70	<i>✓</i>
Stabilizer Bar <i>NA</i>	1	\$ 326.80	\$ 326.80	<i>X</i>
Stabilizer Bar Link <i>NA</i>	1	\$ 92.10	\$ 92.10	<i>X</i>
Front Suspension Lower Arm (RH) <i>to destination</i>	1	\$ 596.80	\$ 596.80	<i>✓</i>
Knuckle Arm (RH) <i>to destination</i>	1	\$ 663.60	\$ 663.60	<i>✓</i>
ABS Sensor <i>NA</i>	1	\$ 290.00	\$ 290.00	<i>X</i>
Brake hose (RH) <i>NA</i>	1	\$ 234.60	\$ 234.60	<i>X</i>
INVERTER COOLANT <i>NA</i>	1	\$ 65.00	\$ 65.00	<i>X</i>
<i>12148.9050</i> SUB TOTAL			\$ 28,480.74	
LESS 20%			\$ 5,696.15	
<i>9718.80</i> DISCOUNTED TOTAL			\$ 22,784.59	
Emblem-Blue Drive (RH) <i>NA</i>	1	\$ 26.60	\$ 26.60	<i>✓</i>
Front Door Comfort Logo (RH) <i>NA</i>	1	\$ 75.00	\$ 75.00	<i>✓</i>
Front Tyre (RH) <i>✓</i>	1	<i>75.00</i> SN	\$ 216.00	<i>X</i>
SUB TOTAL			\$ 317.60	
<b>Labour Charge</b>				
Panel Beating	1	\$1,400.00	\$1,400.00	<i>Foot</i>
Spray Painting Charge	1	\$1,200.00	<del>\$1,200.00</del>	<i>Foot</i>
Wiring Charge	1	\$120.00	\$120.00	<i>30/-</i>
Tuff Kote	1	\$120.00	<del>\$120.00</del>	<i>40/-</i>
Towing Charge	1	\$80.00	\$80.00	<i>NA</i>
Transfer of Door Mechanism FRONT	1	\$80.00	<i>60/-</i> <del>\$80.00</del>	<i>NA</i>
Re-set Frt Power Window System	1	\$200.00	\$200.00	<i>NA</i>
Four Wheel Alignment	1	\$120.00	<del>\$120.00</del>	<i>60/-</i>
Remove/Refix Undercarriage (Frt)	1	\$400.00	<del>\$400.00</del>	<i>150/-</i>
Re-set Frt ABS System	1	<i>1920.00</i> \$200.00	\$200.00	<i>NA</i>
Remove/Refix Radiator	1	\$90.00	\$90.00	<i>NA</i>
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00	<i>NA</i>
Remove/Refix Engine	1	\$600.00	\$600.00	<i>NA</i>
Front Chassis Alignment Charge	1	\$220.00	\$220.00	<i>NA</i>
Remove/Refix Steering Rack/Wheel/Dr Shaft	1	\$150.00	\$150.00	<i>NA</i>
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	<del>\$550.00</del>	<i>180/-</i>
<b>TOTAL LABOUR</b>			\$5,660.00	
<b>ESTIMATE TOTAL</b>			\$ 28,762.19	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*07/07/2025 07:00/08:25 e 1700hrs*  
*NA Antenna*  
*Part by Part. Check Part Prices.*  
*8 days*  
*11713.80*  
*Supp 1443.12*  
*P/P 13156.92*  
*Jan*  
*LKK Antu*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 8-Jul-20

INSURANCE: MSIG

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC2375U (S)

	QTY	UNIT PRICE	TOTAL PRICE
Engine Crossmember <i>distorted</i>	1	\$ 1,803.90	\$ 1,803.90
<b>SUB TOTAL</b>			<b>\$ 1,803.90</b>
<b>LESS 20%</b>			<b>\$ 360.78</b>
<b>DISCOUNTED TOTAL</b>			<b>\$ 1,443.12</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*Ryan*

2 KK Auto

*R*

Phone Number:

Fax Number:

Customer:		Date:	8/7/2020 4:26 PM
Company:		VIN	
License NO:	SHC2375U	Technician:	
Odometer:		Order NO:	

### VEHICLE ALIGNMENT REPORT

HYUNDAI, IONIQ hybrid 17> AE Series All Models, 17-17 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	4°54'	4°00'	5°00'	5°13' *
		Right	4°57'	4°00'	5°00'	5°15' *
	Camber	Left	-1°10' *	-1°00'	0°00'	-0°56'
		Right	-5°10' *	-1°00'	0°00'	-5°16' *
	Toe	Left	1°32' *	-0°02'	0°05'	0°00'
		Right	1°13' *	-0°02'	0°05'	2°46' *
Total		2°45' *	-0°04'	0°11'	2°46' *	
Rear	Camber	Left	-2°10' *	-1°25'	-0°25'	-2°02' *
		Right	-1°40' *	-1°25'	-0°25'	-1°39' *
	Toe	Left	0°09'	0°00'	0°11'	0°08'
		Right	-0°01' *	0°00'	0°11'	-0°01' *
		Total	0°08'	0°00'	0°22'	0°07'
Thrust Angle		-0°05'	---		-0°05'	
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		14°27' *	13°18'	14°18'	14°27' *
	Right		13°48'	13°18'	14°18'	13°48'
Included Angle	Left		13°17'	---	---	13°30'
	Right		8°37'	---	---	8°31'
Toe Out On Turns	Left		---	---	---	---
	Right		---	---	---	---
Max Turn Inside	Left		---	38°00'	41°00'	---
	Right		---	38°00'	41°00'	---
Toe Curve Change	Left		---	---	---	---
	Right		---	---	---	---
Setback	Front		0.08"	---	---	0.08"
	Rear		-0.11"	---	---	-0.11"
Track Width Diff.			-1.03"			-1.03"
Wheel Base Diff.			0.19"			0.19"
Front Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Rear Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Frame Angle						---