

ASS. REC. BY:

REF:

292F

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMT 9939Bat Workshop m/s Volkswagenof 247, ALEXANDER RD

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 132K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMT 9939BYr Regn: 2012 / FEBType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: VolkswagenSHARAN 2.0 TSI c.c. 1584Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 13808

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WUW22Z7WZK V006997Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: _____

F: 225/50R17R: ✓

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

CONTINENTAL

Front

Rear

R/Bal. 6 mm

mm

R/Bal. 6 mm

mm

L/Bal. 6 mm

mm

L/Bal. 6 mm

mm

D.O.A. 03/01/2020D.O.I. 09/07/2020Survey held at Volkswagen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.B.R. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	292F
Vehicle No.:	SMJ9939B
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jul 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SHARAN 2.0 TSI 7N24MY
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	DED033910
Chassis No.:	WVWZZZ7NZKV006997
Maximum Power Output:	162.0 kW (217 bhp)
Open Market Value:	\$35,452.00
Original Registration Date:	22 Feb 2019
First Registration Date:	22 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$41,633.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Feb 2029
PARF Rebate Amount:	\$31,224.00

Intended COE Rebate Details

COE Expiry Date:	21 Feb 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,989.00
COE Rebate Amount:	\$29,254.00
Total Rebate Amount:	\$60,478.00

The information contained herein is correct as at 13 Jul 2020

OK

22 Feb 2019



Used 2018 Volkswagen Sharan 2



Merimen e-Claims



PARF/COE

carmart.com/used_cars/info.php?ID=891155&DL=3028

Volkswagen Sharan 2.0A TSI Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map

**360 VR CARS**A subsidiary of **360 HOLDINGS**

Price \$126,888

Depreciation \$13,040 /yr
View models with similar depreReg Date 31-Aug-2018
(8yrs 1mth 17days COE left)

Mileage 29,000 km (15.5k /yr)

Manufactured 2018

Road Tax \$1,194 /yr

Transmission Auto

Dereg Value \$59,117 as of today (change)

OMV \$35,372

COE \$34,381

ARF \$41,521

Engine Cap 1,984 cc

Power 162.0 kW (217 bhp)

Curb Weight 1,790 kg

No. of Owners 1

Type of Vehicle MPV

Features

Almost New! Very Sporty Looking Facelift 2018 Gen2 Highline Model! 1 Immaculate Owner! Most Powerful 7 Seater In The MPV Segment-GTi Engine! View specs of the Volkswagen Sharan (2011)