

CC 4/ALG 20007060/Ties 3

ASS. REC. BY: Taylor

REF:

ALG

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

lim TS

Veh No: SHE 72435 Yr Regn: 2016 / Aug.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140 c.c. 1685Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 555279 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLR41UM64092625

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16R: u u

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 7/7/20Survey held at Cambridge City

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

Rep. Form: _____

Lump Sum / L.B. (\$ _____)

RE: Accident involving SHC7243J and your insured SMC8601T dated 06.07.2020

AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>

Tue 7/7/2020 11:55 AM

To: Lim Tien Siong <limts@cdge.com.sg>

CAUTION : This email originated from an external party outside ComfortDelGro. Do not click on links or open attachment unless you know the sender.

Hi Sir,

We'll appoint LKK to conduct survey.

Thanks.

AIG Claims Survey

From: Lim Tien Siong [mailto:limts@cdge.com.sg]

Sent: Tuesday, July 07, 2020 11:25 AM

To: AIG SGP, Claims-Survey

Cc: Wong, Ken-FK

Subject: [EXTERNAL] Accident involving SHC7243J and your insured SMC8601T dated 06.07.2020

This message is from an external sender; be cautious with links and attachments.


Officer in charge,

Best Regards,

Lim Tien Siong

Taxi Accident Repair / ComfortDelgro Engineering Pte Ltd

Off:62148398 / Fax:65468156



From: canon@comfortdelgro.com.sg <canon@comfortdelgro.com.sg>

Sent: Tuesday, 7 July 2020 11:20 AM

To: Lim Tien Siong <limts@cdge.com.sg>

Subject: Scan Image

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]