

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGS3396E (Insd veh)	Model:	CHEVROLET CRUZE NB 1.6 D 6AT (A)
	SJG1808A (TP veh)		
Date of Accident:	07/07/2020		

Global Sum Settlement	:	[] Yes	[X] No		
Repair Estimate	:	\$		17,479.60	
Final Repair Cost	:	\$		7,790.30	
Loss of Use	:	\$		days at \$0.00 per day	
Rental (if any)	:	\$		6	days
LTA / GIA Search Fee	:	\$		7.45	
Others:	:	\$		0.00	
	:	\$			
Final Settlement Sum	:	\$		8,397.75	

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____100____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Xin Hua Workshop Pte Ltd	:	8,397.75
2)		:	
3)		:	
4)		:	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

10 Jun 2021

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)