ASS. REC. BY: Kenneth

REF: AIG / 20007135/Ke

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: City Auto

of _____

Insured: 899N

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1-B-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBH 1604K Yr Regn: 02, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or (A)

Make: Toy Hiace c.c 2982

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp.Reading: 55466 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KDH20 · 0228318

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl: NI / S/Rim / STD A/Rim or _____

Tyre Size: F: 195R15X8

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	9 mm	R/Bal.	6 mm
L/Bal.	9 mm	L/Bal.	6 mm
D.O.A.	6/7/20	D.O.I.	9/7/2020

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	

Date/Time, File Pass to? 1) _____ ☐ : Prell. Report ☐ : Final Report

Date/Time, File Return to? 2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation: S - RS __ SI

Add Fee: ☐ : Site Insp ($ _____) ☐ : Interview ($ _____) ☐ Tech Invs ($ _____) ☐ Weekend ($ _____)

Report Format :

Lump Sum / I.B.I: ($ _____)

TOTAL

Scanned with CamScanner